



Obsolete Product List

Updated on November 29th 2005

Part Number	Status	Replace with:	Notes:
5PEEP	Obsolete	5PEEP-M	
8PEEP	Obsolete	8PEEP-M	
10PEEP	Obsolete	5PEEP-M	Two required
16PEEP	Obsolete	8PEEP-M	Two required
24PEEP	Obsolete	8PEEP-M	Three required
3PB	Obsolete	None	
5PB	Obsolete	5PB-M	
8PB	Obsolete	8PB-M	
10PB	Obsolete	5PB-M	Two required
16PB	Obsolete	8PB-M	Two required
24PB	Obsolete	8PB-M	Three required
CS112-75	Obsolete	CS112-100	
CS3-75	Obsolete	CS3-100	
CS6-75	Obsolete	CS6-100	
CSX	Obsolete	DSXL	
CSX-D	Obsolete	DSXL-D	
DSX	Obsolete	DSXL	
DSX-D	Obsolete	DSXL-D	
PSX	Obsolete	PSXL	
PSX-D	Obsolete	PSXL-D	
LSX	Obsolete	LSXL	
DC50LN+xx	Recommended Replacement	CGXJ+xx	Select Voltage
GC50LN+xx	Recommended Replacement	CGXJ+xx	Select Voltage
DC50LNZ+xx	Recommended Replacement	CGXZ+xx	Select Voltage
Ilxxx-xx-xxxA	Obsolete	None	All others
IS-7WFU	Obsolete	None	
IS-12WFU	Obsolete	None	
IS-158E	Obsolete	None	
IS-318E	Obsolete	None	
HPGT-2500	Recommended Replacement	None	End 2006
HPGT-5000	Recommended Replacement	None	End 2006
HPGT-xxxx	Obsolete	None	All others
IS-CF50HD	Recommended Replacement	DSXL-D	
IS-CF50HN	Recommended Replacement	DSXL	
IS-CT50HD	Recommended Replacement	DSXL-D	
IS-CT50HN	Recommended Replacement	DSXL	
IS-PF50HD	Recommended Replacement	DSXL-D	
IS-PF50HN	Recommended Replacement	DSXL	
IS-PT50HD	Recommended Replacement	DSXL-D	
IS-PT50HN	Recommended Replacement	DSXL	
IS-CLF50HD	Obsolete	DSXL-D	
IS-CLF50HN	Obsolete	DSXL	
IS-CLF50LD	Obsolete	DSXL-D	
IS-CLF50LN	Obsolete	DSXL	
IS-MF50HD	Obsolete	DSXL-D	
IS-MF50LD	Obsolete	DSXL-D	
IS-MF50LN	Obsolete	DSXL	
IS-CU50HN	Recommended Replacement	UHF50HN	
IS-VU50HN	Recommended Replacement	VHF50HN	
IS-SB75F	Recommended Replacement	MDS+24-F-F	
IS-DB75F	Recommended Replacement	MDS+24-F-F	Two required
IS-MH50LN	Recommended Replacement	DSXL	
IS-ML50LN	Recommended Replacement	DSXL	
IS-MR50LN	Recommended Replacement	DSXL	
IS-MT50LN	Recommended Replacement	DSXL	



Obsolete Product List

Updated on November 29th 2005

Part Number	Status	Replace with:	Notes:
IS-MU50LN	Recommended Replacemnt	LSXL	
IS-PSP-120	Obsolete	PSP-120	UL LISTED
IS-PSP-240	Obsolete	PSP-240	UL LISTED
IS-TWAX	Obsolete	None	
IS-ST50HN	Obsolete	VHF50HN	
IS-TT50HN	Obsolete	VHF50HN	
IS-UT50HN	Obsolete	VHF50HN	
IS-MR50LNZ+6	Recommended Replacemnt	DGXZ+06NFNF-A	
IS-MR50LNZ+6/V	Obsolete	DGXZ+06NFNF-A	
MR50LNZ+15	Recommended Replacemnt	DGXZ+15NFNF-A	
MM50MDZ+15	Obsolete	DGXZ+15DFDF-A	
MM50MDZ+6	Obsolete	DGXZ+06DFDF-A	
MM50MNZ+15	Obsolete	DGXZ+15NFNF-A	
MM50MNZ+6	Obsolete	DGXZ+06NFNF-A	
MR50MDZ+15	Obsolete	DGXZ+15DFDF-A	
MR50MDZ+6	Obsolete	DGXZ+06DFDF-A	
MR50MNZ+15	Obsolete	DGXZ+15NFNF-A	
MR50MNZ+6	Obsolete	DGXZ+06NFNF-A	
RACK ISO KIT 23	Obsolete	None	
SPT	Obsolete	None	
Cu PRIMER KIT	Obsolete	None	
Grounding Video	Obsolete	None	
GSIE-8	Obsolete	None	
GSIE-12	Obsolete	None	
IS-75NB/1.5	Obsolete	None	
IS-75NB/1.5-MA	Obsolete	None	
IS-75NB/1.5-ME	Obsolete	None	
IS-75NB/6	Obsolete	None	
IS-75NB/6-MA	Obsolete	None	
IS-75NB/6-ME	Obsolete	None	
IS-75NB/18	Obsolete	None	
IS-75NB/18-MA	Obsolete	None	
IS-75NB/18-ME	Obsolete	None	
IS-75UB/1.5	Obsolete	None	
IS-75UB/1.5-MA	Obsolete	None	
IS-75UB/1.5-ME	Obsolete	None	
IS-75UB/6	Obsolete	None	
IS-75UB/6-MA	Obsolete	None	
IS-75UB/6-ME	Obsolete	None	
IS-75UB/18	Obsolete	None	
IS-75UB/18-MA	Obsolete	None	
IS-75UB/18-ME	Obsolete	None	