



ISO 9001 Registered

SCSI Selection Guide

Part Number	Number of Channels	Mode	Sleep Current (μ A)	Notes
IMP5111	9	SE	275	
IMP5112	9	SE	275	
IMP5115	9	SE	375	DS21S07A Pinout
IMP5121	27	SE	375	
IMP5218	9	SE	275	
IMP5219	9	SE	275	
IMP5225	18	SE	275	
IMP5226	18	SE	275	
IMP5241	9	SE/LVD	35	DS2118 Pinout
IMP5242	9	SE/LVD	35	

SCSI SelGd t01.eps

IMP, Inc. Data Communications

Sales and Distribution Offices



Worldwide Headquarters

IMP, Inc.
2830 North First Street
San Jose, CA 95134
Tel: 408.432.9100
Fax: 408.434.1215
E-mail: info@impinc.com
Internet: www.impweb.com

Asia Pacific Area Sales Office

Philip Wong
IMP, Inc.
391A Orchard Road
#12-01, Ngee Ann City Tower A
Singapore 238873
Tel: 65.838.5046 x225
Fax: 65.235.9340
E-mail: philipw@impinc.com

USA Distributor

Jaco Corporate Headquarters
145 Oser Avenue
Hauppauge, NY 11788
Tel: 516.273.5500
TOLL FREE: 800.989.JACO
E-mail: info@jacoelectronics.com
Internet: www.jacoelectronics.com