

ECR #: 13

Title: Remove SMB1 and SMB0 from connector

Release Date: Feb. 10, 1997

Impact: Change

Spec Version: A.G.P. 1.0

Summary:Remove the SMB0 and SMB1 from the A.G.P. connector.

Background:Currently there is no known reason why these are part of the connector definition.

Change Current Specification as shown:

Remove SMB0 and SMB1 from the table 5-1 and rename pins A66 and B66 as Reserved.