

**Philips Semiconductors
DN51A
MARCH 12, 2004**

ADDITIONAL DISCONTINUED CAEN FIRE PRODUCTS NOT LISTED IN PHILIPS ORIGINAL DN-51 NOTICE DATED FEBRUARY 20, 2003.

SEE DN51A NOTICE LETTER FOR APPLICABLE TERMS, CONDITIONS, AND CODE DEFINITIONS FOR THESE DISCONTINUED PRODUCTS.

REFER TO PHILIPS WEB-SITE "<http://www.semiconductors.philips.com/eol> FOR ADDED INFORMATION.

<u>TYPE CODE:</u>	<u>SOURCE CODE:</u>	<u>AVAILABILITY CODE:</u>
T = Type number fully withdrawn	C = Customer specific product	1 = Non-availability. No last time buy possible
N = Part type packing option only withdrawn	M = Multiple source product	2 = Limited availability (check with your usual sales contact)
	S = Sole source product	3 = Standard availability

Philips Part Number Description	Description	12nc	Type Code	Source Code	Availability Code	Last Time Buy	Last Time Ship	Replacement Part	Customer Comments	MAG
ALP007M/C1	STUBILO DM	935152080118	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TDA5632M/C1	STUBILO DM	935073630118	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TDA5637BM/C1	STUBILO DM	935193100112	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TDA5637BM/C1	STUBILO DM	935193100118	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TDA5637M/C1	STUBILO DM	935170440118	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TDA5736M/C1	STUBILO DM	935179770112	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TDA5736M/C1	STUBILO DM	935179770118	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TDA5736M/C1/M1	STUBILO DM	935274254118	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25

**Philips Semiconductors
DN51A
MARCH 12, 2004**

Philips Part Number Description	Description	12nc	Type Code	Source Code	Availability Code	Last Time Buy	Last Time Ship	Replacement Part	Customer Comments	MAG
TDA5737M/C1	STUBILO DM	935173650112	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TDA5737M/C1	STUBILO DM	935173650118	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TDA6404TS/C1	STUBILO DM	935250380512	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TDA6404TS/C1	STUBILO DM	935250380518	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TDA8012AM/C1	STUBILO DM	935241000118	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TDA8540T/C2	STUBILO DM	935057500112	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TDA8540T/C2	STUBILO DM	935057500118	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TDA8822M/C1	STUBILO TM	935221010112	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TDA8822M/C1	STUBILO TM	935221010118	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TDA8822T/C1	STUBILO TM	935221020112	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TDA8822T/C1	STUBILO TM	935221020118	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TSA5055T/C3	STUBILO DM	935198000512	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TSA5055T/C3	STUBILO DM	935198000518	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25

**Philips Semiconductors
DN51A
MARCH 12, 2004**

Philips Part Number Description	Description	12nc	Type Code	Source Code	Availability Code	Last Time Buy	Last Time Ship	Replacement Part	Customer Comments	MAG
TSA5512M/C3	STUBILO DM	935184350118	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TSA5512T/C3	STUBILO DM	935184340512	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TSA5512T/C3	STUBILO DM	935184340518	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TSA5520M/C4	STUBILO TM	935260424112	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TSA5520M/C4	STUBILO TM	935260424118	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TSA5520M/C4/M1	STUBILO TM	935274358518	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TSA5520T/C4	STUBILO TM	935260788518	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TSA5522M/C1	STUBILO TM	935083080112	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TSA5522M/C1	STUBILO TM	935083080118	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TSA5522T/C1	STUBILO TM	935083070512	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TSA5523M/C1	STUBILO TM	935205860118	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TSA5526AM/C2	STUBILO TM	935260876112	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25
TSA5526AM/C2	STUBILO TM	935260876118	T	S	2	20-Nov-04	20-Feb-05	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.	R25