


Components and materials

Part 8 February 1977



COMPONENTS AND MATERIALS

Part 8

February 1977

Variable mains	transformers	(auto-tran	sformers)	Description of the control of the co
Variable mains	transformers	(separate	windings)	METATA SA AN AND MINISTER MANAGEMENT AND
Accessories		. ,		PARTICIPATION OF THE PARTICIPA
Contents				CONTRACTOR



DATA HANDBOOK SYSTEM

Our Data Handbook System is a comprehensive source of information on electronic components, subassemblies and materials; it is made up of three series of handbooks each comprising several parts.

SEMICONDUCTORS AND INTEGRATED CIRCUITS RED COMPONENTS AND MATERIALS GREEN

The several parts contain all pertinent data available at the time of publication, and each is revised and reissued periodically.

Where ratings or specifications differ from those published in the preceding edition they are pointed out by arrows. Where application information is given it is advisory and does not form part of the product specification.

If you need confirmation that the published data about any of our products are the latest available, please contact our representative. He is at your service and will be glad to answer your inquiries.

This information is furnished for guidance, and with no guarantee as to its accuracy or completeness; its publication conveys no licence under any patent or other right, nor does the publisher assume liability for any consequence of its use; specifications and availability of goods mentioned in it are subject to change without notice; it is not to be reproduced in any way, in whole or in part without the written consent of the publisher.

ELECTRON TUBES (BLUE SERIES)

This series consists of the following parts, issued on the dates indicated.

Part 1a Transmitting tubes for communication and Tubes for r.f. heating Types PE05/25 - TBW15/125

December 1975

Transmitting tubes for communication Part 1b

January 1976

Tubes for r.f. heating Amplifier circuit assemblies

Part 2 Microwave products

May 1976

Communication magnetrons

Magnetrons for microwave heating

Triodes

Diodes

Klystrons

T-R Switches

Travelling-wave tubes

Microwave semiconductor devices

Isolators - circulators

Part 3 Special Quality tubes;

Miscellaneous devices

January 1975

Part 4 Receiving tubes

March 1975

Part 5a Cathode-ray tubes

August 1976

Part 5b, Camera tubes; Image intensifier tubes

May 1975

Part 6 Products for nuclear technology

January 1977

Channel electron multipliers Geiger-Mueller tubes

Neutron tubes

Part 7 Gas-filled tubes

August 1975

Voltage stabilizing and reference tubes Counter, selector, and indicator tubes Trigger tubes

Switching diodes

Ignitrons Industrial rectifying tubes High-voltage rectifying tubes

Thyratrons

Part 8 TV Picture tubes

October 1975

Part 9 Photomultiplier tubes Phototubes (diodes)

June 1976

August 1976

SEMICONDUCTORS AND INTEGRATED CIRCUITS (RED SERIES)

This series consists of the following parts, issued on the dates indicated.

Part 1a Rectifier diodes, thyristors, triacs

March 1976

Rectifier diodes

Voltage regulator diodes (> 1,5 W) Transient suppressor diodes Rectifier stacks Thyristors Triacs

Part 1b Diodes

October 1975

Small signal germanium diodes Small signal silicon diodes

Voltage reference diodes

Voltage regulator diodes (< 1,5 W)

Special diodes

Tuner diodes

Part 2 Low-frequency transistors

December 1975

Part 3 High-frequency and switching transistors

April 1976 June 1976

July 1976

Part 4a Special semiconductors

Transmitting transistors Microwave devices Field-effect transistors Dual transistors
Microminiature devices for
thick- and thin-film circuits

Part 4b Devices for optoelectronics

Displays

Photosensitive diodes and transistors Light emitting diodes Photocouplers Infrared sensitive devices Photoconductive devices

Part 5a Professional analogue integrated circuits

November 1976

N.B. Consumer circuits will be issued in part 5b

Part 6 Digital integrated circuits

May 1976

LOCMOS HE family GZ family

COMPONENTS AND MATERIALS (GREEN SERIES)

This series consists of the following parts, issued on the dates indicated.

	81, 1884	ed on the dates mulcated.
Part 1	Functional units, Input/output devices, Peripheral devices	November 1975
	High noise immunity logic FZ/30-Series Circuit blocks 40-Series and CSA70 Counter modules 50-Series NORbits 60-Series, 61-Series	Circuit blocks 90-Series Input/output devices Hybrid integrated circuits Peripheral devices
Part 2a	Resistors	
	Fixed resistors Variable resistors Voltage dependent resistors (VDR) Light dependent resistors (LDR)	February 1976 Negative temperature coefficient thermistors (NTC) Positive temperature coefficient thermistors (PTC) Test switches
Part 2b	Capacitors	April 1976
	Electrolytic and solid capacitors Paper capacitors and film capacitors	Ceramic capacitors Variable capacitors
Part 3	Radio, Audio, Television	
	FM tuners Loudspeakers Television tuners and aerial input assemblies	January 1977 Components for black and white television Components for colour television
Part 4a	Soft ferrites	
	Ferrites for radio, audio and television Beads and chokes	October 1976 Ferroxcube potcores and square cores Ferroxcube transformer cores
Part 4b	Piezoelectric ceramics, Permanent magnet mater	
Part 5	Ferrite core memory products	July 1975
	Ferroxcube memory cores Matrix planes and stacks	Core memory systems
Part 6	Electric motors and accessories	September 1975
	Small synchronous motors Stepper motors	Miniature direct current motors
Part 7	Circuit blocks	September 1971
	Circuit blocks 100 kHz-Series Circuit blocks 1-Series Circuit blocks 10-Series	Circuit blocks for ferrite core memory drive
Part 8	Variable mains transformers	Echnique 1077
Part 9	Piezoelectric quartz devices	February 1977 March 1976
Part 10	Connectors	watch 1976

November 1975

Part 10

Connectors

INTRODUCTION

APPLICATION

The main fields of our variable transformers are:

distortion free voltage control for measuring equipment voltage stabilizers etc.

power control for electric heating heat sealing of plastics motor speed

current control for galvanizing plants

light control in hotels, cinemas, homes

ventilation control in buildings, livestock houses, greenhouses, etc.

They have the following features:

continuous voltage control

small dimensions and high efficiency by using core material of high quality

very low stray losses by using toroid coil shape and specially treated contact surface with low and stable contact resistance between brush and contact surface resulting in low losses at the most critical place

corrosion proof

long life carbon brushes and smooth contact surface

simple replacement of carbon brushes

simple coupling in parallel or three-phase combinations

adjustable spindle length

low coil resistance

high overload characteristics.

The transformers are arranged by increasing nominal input voltage and, within each block, by increasing current.

A detailed specification can be found in the data sheets.

The data sheets are divided into two sections (with tabbed dividers):

Variable mains transformers (auto-transformers);

Variable mains transformers (separate windings)

Data sheets are arranged according to transformer size code.

Available versions

All transformers are available as panel model and some also as bench model or laboratory model.

A panel model transformer is a transformer of which the live parts are not protected.

A bench model transformer is a bench model transformer in a protective housing and provided with a knob and dial.

A laboratory model transformer is a bench model transformer provided with a handle, a 3-core cable (including earth) with plug for input connection, an outlet socket, and a fuse.

Both plug and socket are of the side-contact earth model (except the socket of the model with separate windings).


The dimensions of the laboratory models are essentially the same as those of the corresponding bench models. See also page S3.


For further information contact your supplier.

Note to page S2

[&]quot;Over-wind" transformers (transformers with a maximum output voltage higher than the input voltage) may be used with the input voltage connected to the complete winding. The permissible output current for this type of connection is given in these columns.

			· ·	see no	te on page	S1				
input voltage		t current	output voltage	outpu	t current	output voltage	trans- former		e no. 242	
nom. V	nom. A	max. A	no-load V	nom. A	max. A	no-load V	size code	panel model	bench model	lab. model
42	4	4,8	0- 42				E2	90031		
60	1,2	1,32	0- 60				E1	00007		
110	0,6	0,7	0-110				E1	00107		
115	1,2 1,4	1,4 1,7	0-130 0-115	1,32	1,54	0-115	E2 E2	01607 11607		
	2,5	3,2	0-150		3,25	0-127	C1	02306		
127	5 10	6,3 12,6	0-150 0-150	5,5 11	6,5 13	0-127 0-127	C2 C3	03306 04306		
	0,7	0,83	0-240	0,77	0,91	0-220	E2	01407		
	0,83	1	0-220		4.0	0.000	E2	11407	00404	
	1	1,25	0-260 0-260	1,1	1,3	0-220 0-220	C1 E3	02406 08407	02401	
	1,2 1,4	1,4	0-200	1,32	1,56	0-220	E3	18407		
	2	2,4	0-260	2,2	2,6	0-220	E4	03407		
ļ	2,5	3	0-220		-,0		E4	13407		}
	2,5	3,2	0-260	2,75	3,25	0-220	C2	03406	03401	03405
220	4	4,8	110-220				E5	90023		
220	4.	4,8	0-220				E5	90024		
	4,5	5	0-253	5	5,85	0-220	E6	90028		
	5	6,3	0-260	9 '	6,5	0-220	C3	04406	04401	04405
	8,5	11,2	0-260		11,5	0-220	C4	05406	05401	05405
	10	12	0-220	g .	45.0	0.000	C4	15406		
	12	15	0-260	13,2	15,6	0-220	E8 E8	06407 16407		
	15 23	18 30	0-220 0-260	25,3	30	0-220	E10	07407	07411	
		-	120- 0	20,3	30	0-220	E10	00407	07411	
	0,5	0,55	120-240 120- 0					00407		
	0,5	0,55	120-240	R			E1	90004		
	0,5	0,55	0-120 240-120	B .			E1	90011		
	1	1,25	0-270	8	1,25	0-240	C1	02506	02501	
040	1,2	1.4	0-260	1,2	1,4	0-240	E3	08407		
240	2	2,4	0-260		2,4	0-240	E4	03507		
	2,5	3,2	0-270	я .	3,2	0-240	C2	03506	03501	
	4,5	5	0-276	12	5	0-240	E6	90028		
	5	6,3	0-270	H	6,3	0-240	C3	04506	04501	
	8,5	11,2	0-270	8,5	11,2	0-240	C4	05506	05501	
	12	15	0-260	3	15	0-240	E8	06507	07544	
	23	30	0-260	23	30	0-240	E10	07507	07511	
		nte winding				T	C4	00006	529	. 00005
220	3	1	0-242	I	L		U4	00000		00005





Variable mains transformers (auto-transformers)





OPERATIONAL NOTES

Deviations from the following are given in the data sheets.

1. General *

A variable mains transformer is an auto-transformer with a secondary voltage which is continuously variable.

The common winding which serves as both primary and secondary is usually a single layer, wound on an annular core. A carbon brush, serving as the movable secondary tap, is made to contact the partly bared winding. The brush track needs no maintenance. The primary may be provided with one or more fixed taps.

2. Input voltage

The input voltage is connected to all or part of the primary of the transformer. In the data sheets the two input terminals for a stated input voltage are indicated. The second letter indicates the common input and output terminal.

Unless otherwise stated the input/output terminals indicated are given so that a clockwise rotation of the spindle results in an increasing output voltage when the transformer is mounted behind a panel.

The nominal input voltage may continuously be exceeded by 10%.

3. Output voltage

The output voltage (at no load) cannot always be set at exactly the same value as the input voltage as the carbon brush contact point with the slider against the end stop does not always coincide with the beginning or the end of the winding. The deviation from the exact value is given in volts.

4. Terminals

The input terminals are denoted N, K, L or M.

Z is a mid-tap.

The output voltage is taken between T (carbon brush) and one of the other terminals.

5. Nominal output current

This is the current which the transformer may continuously supply under the most unfavourable brush condition and ambient temperature.

^{*)} Not applicable to variable mains transformers with separate windings.

6. Continuous overload (Maximum output current)

In an auto-transformer the distribution of the currents, and consequently the copper losses and heat generation in the windings, depends on the brush position. The nominal continuous current is defined by the most unfavourable brush position and the cooling capacity of the transformer. Starting from that cooling capacity it is obvious that the output current may be adapted to the brush position. Measurements have shown that a certain overload is permissible within 10% from the primary tappings. In the graphs, Fig. 1, Fig. 2 and Fig. 3, the maximum load current is plotted as a function of the no-load output voltage which corresponds with the brush position. For the values of input voltage, nominal output current and maximum output current see under "Electrical data" in the data sheets.

If any doubt arises as to the cooling, do not overload the transformer. A considerable overload can be tolerated if the transformer, and especially the brush track contact, is artificially cooled or immersed in oil. Since this depends greatly on given circumstances, the only hard-and-fast directive is that the temperature rise (ΔT) of the brush track contact may not exceed 70 °C or 90 °C (see the relevant data sheet), or the maximum temperature is attained (see Fig. 6).




Fig. 1. Maximum load as a function of the output voltage; input voltage
M to K or L to N.



7Z66594.2

When the ends of the winding are used as input terminals, an even higher overload is permitted.




Fig. 2. Maximum load as a function of the output voltage; input voltage N to K.

For a transformer without taps the maximum load as a function of the output voltage is given in Fig. 3.




Fig. 3. Maximum load as a function of the output voltage; input voltage N to K.

7. Momentary overloads

High momentary overloads can be permitted due to the construction of the brush track and of the brush gear.

The curve (Fig. $\overline{4}$) gives the relation between maximum permissible load and time. It is based on the maximum permissible temperature of the brush and on the unfavourable brush position. Therefore, after occasional overloading, no additional cooling of the transformer is required.




Fig. 4. Maximum non-repetitive overload as a function of time.

For other output voltages the curve can be combined with the overload curve above. To avoid damage to the brush and the track the absolute limit for instantaneous loads is 1000%.

8. Overload protection and inrush current

Protection of the transformer can be effected by inserting appropriate overload protection in the output line.

Due to the high permeability of the core material, high inrush currents (up to 20 times the nominal current) may occur. Although these last only a few cycles, and will not damage the transformer, primary fuses may be blown. It is therefore necessary to employ delayed fuses or other delayed protection devices.

9. Voltage per turn of winding

The smallest step of voltage regulation (finest resolution) is that which occurs as the carbon brush "switches over" from one turn of the winding to the next.



10. Voltage drop

Due to copper and brush losses the output voltage will drop in proportion to the output current.

The curves (Fig. 5) show the voltage drop as a percentage of the maximum voltage drop given in the data sheets as a function of brush setting.

The upper curve applies to a constant current load (nominal output current). The lower curve applies to a constant impedance load (current approximately proportional to the voltage, increasing to maximum current at nominal input voltage).




Fig. 5. Voltage drop as a function of brush setting.

11. Losses, no load

The core material has a practically constant specific no-load loss for frequencies of 50 to 400 Hz. The values given in the data sheets, refer to a mains frequency of 50 Hz. For lower frequencies the mains voltage must be decreased proportionally to avoid saturation of the core, and hence excessive core losses. Theoretically, the mains voltage can be increased for higher frequencies. However, the brush losses, being related to the voltage per turn of winding, would cause overheating of the brush contact point. For this reason it is not advisable to increase the input voltage.

12. Ambient temperature range

The data refer to an ambient temperature range of $-15\ to\ +40\ ^{o}C$. See also following paragraph.

13. Derating for higher ambient temperatures

The nominal data refer to a maximum ambient temperature of $40\ ^{o}\text{C}$. For higher temperatures the current must be derated in conformity with the curves of the figure below. These curves are also based on the most unfavourable brush position and should be combined with figures of preceding pages for different conditions.




Fig. 6. Maximum permissible output current as a function of temperature.

Curve a applies to transformers for which the maximum permissible temperature rise at any point is 90 °C.

Curve b applies to transformers for which the maximum permissible temperature rise at any point is 70 °C.

14. Frequency range

The transformers may be used at frequencies between 50 and 400 Hz. See also "Losses, no load".

15. Insulation resistance

The insulation resistance between live and non-live parts after the damp heat test (IEC 68-2-3, test Ca, 21 days) is >5 M Ω .

16. Test voltage

All transformers are tested for 1 min at 2000 V, 50 Hz.



17. Air gap

The air gap between live and non-live parts is ≥ 4 mm.

18. Leakage path

The leakage path between live and non-live parts is ≥ 5 mm.

19. Earthing the output circuit

If it necessary to earth the output circuit, an isolating transformer must be connected between the mains and the variable transformer, so as to prevent short circuits.

20. Angle of rotation

The total angle of rotation is $\approx 320^{\circ}$.

21. Life

The guaranteed life of the variable mains transformers, if used within the ratings, is $> 100\,000$ two-way turns, however, the life expectancy is $\ge 250\,000$ two-way turns.

22. Parallel connection

For parallel connection of two or more transformers, chokes should be inserted between the secondaries to prevent high interchange currents caused by small differences in ganging.

See Handbook section "Accessories".

23. Environmental tests

The transformers are designed to meet the following tests:

Damp heat test

IEC 68-2-3, test Ca, 21 days

Temperature cycling

IEC 68-2-14, test Na, $-10/\!\!+\!85$ °C, 1 cycle

Shock test

IEC 68-2-27, test Ea

Acceleration, peak, $30 \text{ g} (294 \text{ m/s}^2)$

Pulse duration 6 ms

Number of shocks 3 in 3 x 2 directions

Vibration test

IEC 68-2-6, test Fc, Procedure B4

10-55-10 Hz, 1 oct./min, amplitude 0,35 mm, 3 x 2 h

24. Climatic category

The climatic category of the transformers is, according to IEC 68-1: 15/040/21.

=

OPERATIONAL NOTES VARIABLE MAINS TRANSFORMERS

25. Accessories

A wide range of accessories is available:

Control knobs
Ganging units
Motor drive modules
Chokes for parallel connection of transformers
A.C. stabilizer module
See Handbook section "Accessories".



VARIABLE MAINS TRANSFORMERS transformer size code C1

QUICK REFERENCE DATA						
input voltage output current out put voltage catalogue numb (V) (A) (V) 2422 530						
			bench model	panel model		
127/150 220/260 240/270	2,5 1 1	0 to 150 0 to 260 0 to 270	02401 02501	02306 02406 02506		

To be read in conjunction with "Operational notes Variable mains transformers".

APPLICATION

These panel mounting or bench model transformers are designed for use in laboratories and in industrial and professional equipment.

DESCRIPTION

These transformers have a single layer of copper wire wound on an annular core. This part is vacuum-impregnated and it is mounted in a discast aluminium frame. The construction permits an adjust ment down to exactly $0\ V$.


The fixed-length spindle protrudes at both sides; the amount of side-to-side protrusion is adjustable. The spindle can be easily replaced by one of another length. Screw terminals are provided for connecting the leads.

The bench models can also be used for panel mounting.


TRANSFORMERS SIZE CODE CI

ELECTRICAL DATA

Circuit diagram



KL = NM Z = centreltap



panel model

bench model

	2422	2422 530		
	02306	02401 02406	02501 02506	
Input voltage L to N * K to N		1	240 V + 10% 270 V + 10%	
Output voltage T to N 1)	0 to ≥150 V	0 to ≥260 V	0 to ≥270 V	
Nominal output current over the whole control range	2,5 A	1 A	1 A	
Maximum output current 2)	3, 2 A	1, 25 A	1,25 A	
Voltage per turn of winding	0,4 V	0, 38 V	0,39 V	
Voltage drop at nominal output curren	(3) $\leq 6 \text{ V}$	≤ 13 V	≤ 13 V	
Losses, no load	≤ 7. W	≤ 5 W	≤ 6, 2 W	
Permissible temperature rise at any point 4)	max. 90 °C	max. 70 °C	max. 70 ^o C	

^{*} Second letter denotes the common input/output terminal.




The input voltage is stated for clockwise rotation when the transformer is mounted behind a panel.

²⁾ See "Operational notes" paragraph "Continuous overload".


³⁾ See "Operational notes" paragraph "Voltage drop".

⁴⁾ See "Operational notes" paragraph "Derating for higher ambient temperatures".


MECHANICAL DATA



Dimensions in mm



panel model



The pads protrude approximately 5 mm.

bench model

TRANSFORMERS SIZE CODE CI

VARIABLE MAINS TRANSFORMERS

Degree of protection (IEC144)

bench models IP20 panel models IP00

Mass

panel model $\approx 2,4$ kg bench model $\approx 2,8$ kg

Operating torque 0,07 to 0,15 Nm

Permissible end stop torque max. 4 Nm

Mounting

Mounting position: any.

The transformer can be fitted to a panel or a chassis by means of 3 screws M4 (maximum length = panel thickness +9,5 mm).

The pads of the bench models have to be removed before mounting.

Carbon brushes

Spare carbon brushes can be supplied under catalogue number $4322\ 026\ 19310$ (or service number $5322\ 362\ 40011$).

ACCESSORIES

Available accessories:

Control knobs.

Ganging units. See Handbook section "Accessories".

Motor drive module. Use transformer size code C1 at selecting accessories.

A.C. stabilizer module.

Further information on request.



VARIABLE MAINS TRANSFORMERS transformer size code C2

QUICK REFERENCE DATA						
input voltage (V)	output current (A)	output voltage catalogue number (V) 2422 530				
			bench model	panel model	lab. model	
127/150 220/260 240/270	5 2,5 2,5	0 to 150 0 to 260 0 to 270	03401 03501	03306 03406 03506	03405	

To be read in conjunction with "Operational notes Variable mains transformers".

APPLICATION

These panel mounting, bench model and laboratory model transformers are designed for use in laboratories and in industrial and professional equipment.

DESCRIPTION

These transformers have a single layer of copper wire wound on an annular core.

This part is vacuum-impregnated and mounted in a diecast aluminium frame.

The construction permits an adjustment down to exactly 0 V.

The fixed-length spindle protrudes at both sides; the amount of protrusion is adjustable.

The spindle can be easily replaced by one of another length.

Screw terminals are provided for connecting the leads.

The bench models can also be used for panel mounting.

The laboratory model is a bench model provided with a cable with plug, a fuse,


a socket, and a handle. See also drawing page S3.




TRANSFORMERS SIZE CODE C2

ELECTRICAL DATA

Circuit diagram







bench model ** 7Z68474.

max. 90 °C

•		2422 530		
		03306	03401 03406	03501 03506
Input voltage L to N * K to N		127 V + 10% 150 V + 10%	220 V + 10% 260 V + 10%	240 V + 10% 270 V + 10%
Output voltage T to N	1)	0 to ≥150 V	0 to ≥260 V	0 to ≥270 V
Nominal output current		5 A	2,5 A	2,5 A
Maximum output current	²)	6, 3 A	3, 2 A	3, 2 A
Voltage per turn of winding		0,5 V	0,48 V	0,51 V
Voltage drop at nominal output current	³)	≤ 5 V	≤ 9 V	≤ 9 V
Losses, no load		≤ 7 W	≤ 8 W	≤ 8,5 W>
Permissible temperature rise				

4)



at any point

^{*} Second letter denotes the common input/output terminal.

^{**} Circuit diagram laboratory model see page S3.


The output voltage is stated for clockwise rotation when the transformer is mounted behind a panel.

²⁾ See "Operational notes" paragraph "Continuous overload".


³⁾ See "Operational notes" paragraph "Voltage drop".

⁴⁾ See "Operational notes" paragraph "Derating for higher ambient temperatures".


MECHANICAL DATA




Dimensions in mm



panel model



For laboratory model see page S3.



The pads protrude approximately 5 mm.

bench model



VARIABLE MAINS TRANSFORMERS

TRANSFORMERS SIZE CODE C2

Degree of protection (IEC144)

bench model IP20 panel model IP00

Mass

panel model $\approx 3,65 \text{ kg}$ bench model $\approx 4,1 \text{ kg}$ laboratory model $\approx 4,35 \text{ kg}$

Operating torque 0,1 to 0,2 Nm

Permissible end stop torque max. 4 Nm

Mounting

Mounting position: any.

The transformer can be fitted to a panel or a chassis by means of 3 screws M4 (maximum length = panel thickness + 10 mm). The pads of the bench models have to be removed before mounting.

Carbon brushes

Spare carbon brushes can be supplied under catalogue number $4322\ 027\ 75160$ (service number $5322\ 362\ 40044$).

ACCESSORIES

Available accessories:

Control knobs.
Ganging units.
Motor drive module.
A.C. stabilizer module.

Further information on request.

See Handbook section "Accessories". Use transformer size code C2 at selecting accessories.



VARIABLE MAINS TRANSFORMERS transformer size code C3

·	QUICK REFERENCE DATA						
input voltage (V)	output current (A)	output voltage (V)	catalo 2422				
			bench model	panel model	lab, model		
127/150 220/260 240/270	10 5 5	0 to 150 0 to 260 0 to 270	04401 04501	04306 04406 04506	04405		

To be read in conjunction with "Operational notes Variable mains transformers".

APPLICATION

These panel mounting, bench model and laboratory model transformers are designed for use in laboratories and in industrial and professional applications.

DESCRIPTION

These transformers have a single layer of copper wire wound on an annular core.

This part is vacuum-impregnated and mounted in a diecast aluminium frame.

The construction permits an adjustment down to exactly 0 V.

The fixed-length spindle protrudes at both sides: the amount of protrusion is adjustable.

The spindle can be easily replaced by one of another length.

Screw terminals are provided for connecting the leads.

The bench models can also be used for panel mounting.

The laboratory model is a bench model provided with a cable with plug, a fuse,


a socket, and a handle. See also drawing page S3.




December 1976 C3-1

ELECTRICAL DATA

Circuit diagram







bench model **

		2422 530		
		04306	04401 04406	04501 04506
Input voltage L to N * K to N		, ,	, , ,	240 V + 10% 270 V + 10%
Output voltage T to N	¹)	0 to ≥150 V	0 to ≥260 V	0 to ≥270 V
Nominal output current		10 A	5 A	5 A
Maximum output current	²)	12, 6 A	6, 3 A	6,3 A
Voltage per turn of winding		0,65 V	0, 63 V	0,66 V
Voltage drop at nominal output current	3)	≤ 5 V	≤ 6 V	≤ 6 V
Losses, no load		≤ 10,5 W	≤ 9 W	≤ 10,5 W
Permissible temperature rise at any point	4)	max	90 °C	

^{*} Second letter denotes the common input/output terminal.



^{**} Circuit diagram laboratory model see page S3.

¹⁾ The output voltage is stated for clockwise rotation when the transformer is mounted behind a panel.


²⁾ See "Operational notes" paragraph "Continuous overload".


³⁾ See "Operational notes" paragraph "Voltage drop".

⁴⁾ See "Operational notes" paragraph "Derating for higher ambient temperatures".


MECHANICAL DATA

Dimensions in mm






panel model



For laboratory model see page S3.



The pads protrude approximately 5 mm.

bench model

TRANSFORMERS SIZE CODE C3

VARIABLE MAINS TRANSFORMERS

Degree of protection

bench model IP20 panel model IP00

Mass

panel model $\approx 6 \text{ kg}$ bench model $\approx 6,6 \text{ kg}$ laboratory model $\approx 6,9 \text{ kg}$

Operating torque 0, 15 to 0, 25 Nm

Permissible end stop torque

Mounting

Mounting position: any.

The transformer can be fitted to a panel or a chassis by means of 3 screws M6 (maximum length = panel thickness + 10 mm). The pads of the bench models have to be removed before mounting.

Carbon brushes

Spare carbon brushes can be supplied under catalogue number 4322 027 75160 (service number 5322 362 40044).

ACCESSORIES

Available accessories:

Control knobs.
Ganging units.
A.C. stabilizer module.
Chokes for parallel connection.
Motor drive module.

Further information on request.

See Handbook section "Accessories". Use transformer size code C3 at selecting accessories.

max. 4 Nm



VARIABLE MAINS TRANSFORMERS transformer size code C4

QUICK REFERENCE DATA						
input voltage (V)	output current (A)	output voltage (V)	catalogue number 2422 530			
			bench model	panel model	lab. model	
220 220/260 240/270	10 8,5 8,5	0 to 220 0 to 260 0 to 270	-05401 05501	15406 05406 05506	05405	

To be read in conjunction with "Operational notes Variable mains transformers".

APPLICATION

These panel mounting, bench model and laboratory model transformers are designed for use in laboratories and in industrial and professional equipment.

DESCRIPTION

These transformers have a single layer of copper wire wound on an annular core.

This part is vacuum-impregnated and mounted in a diecast aluminium frame.

The construction permits an adjustment down to exactly 0 V.

The fixed-length spindle protrudes at both sides: the amount of protrusion is adjustable.

The spindle can be easily replaced by one of another length.

Screw terminals are provided for connecting the leads.

The bench models can also be used for panel mounting.


The laboratory model is a bench model provided with a cable with plug, a fuse,


a socket, and a handle. See also drawing page S3.




ELECTRICAL DATA

Circuit diagram







panel model 2522 530 15406 only

panel model

bench model **

		154
Input voltage L to N * K to N		220
Output voltage T to N	¹)	0 to
Nominal output current		10 4
Maximum output current	2)	12 2
Voltage per turn of winding		0,8
Voltage drop at nominal output current	3)	≤4
Losses, no load		≤ 16
Permissible temperature rise at any point	⁴)	-

15406	05401 05406	05501 05506
220 V + 10%	220 V + 10% 260 V + 10%	240 V + 10% 270 V + 10%
0 to ≥220V	0 to ≥260 V	0 to ≥270 V
10 A	8, 5 A	8,5 A
12 A	11, 2 A	11, 2 A
0,81 V	0,81 V	0,85 V
' ≤4 V	≤6 V	≤ 6 V
≤ 16 W	≤ 16 W	≤ 17,5 W

2422 530

max. 90 °C

^{*} Second letter denotes the common input/output terminal.

^{**}Circuit diagram laboratory model see page S3.

¹⁾ The output voltage is stated for clockwise rotation when the transformer is mounted behind a panel.


²⁾ See "Operational notes" paragraph "Continuous overload".


³⁾ See "Operational notes" paragraph "Voltage drop".

⁴⁾ See "Operational notes" paragraph "Derating for higher ambient temperatures".


MECHANICAL DATA

Dimensions in mm






panel model



For laboratory model see page S3.



The pads protrude approximately 5 mm.

bench model



VARIABLE MAINS TRANSFORMERS

Degree of protection (IEC144)

bench model IP20 panel model IP00

Mass

panel model $\approx 8.8 \text{ kg}$ bench model $\approx 9.6 \text{ kg}$ laboratory model $\approx 9.85 \text{ kg}$

Operating torque 0, 2 to 0, 3 Nm

Permissible end stop torque max. 4 Nm

Mounting

The transformer can be fitted to a panel or chassis by means of 3 screws M6 (maximum length = panel thickness + 11 mm). The pads of the bench models have to be removed before mounting.

Carbon brushes

Spare carbon brushes can be supplied under catalogue number $4322\ 027\ 75160$ (service number $5322\ 362\ 40044$).

ACCESSORIES

Available accessories:

Control knobs.
Ganging units.
Motor drive module.
A.C. stabilizer module.
Chokes for parallel connection.
Further information on request.

See Handbook section "Accessories". Use transformer size code C4 at selecting accessories.



VARIABLE MAINS TRANSFORMERS moulded type; transformer size code El

QUICK REFERENCE DATA			
input voltage (V)	output current	output voltage (V)	catalogue number 2422 530
240	0,5	120 to 0 or 120 to 240	00407
120 or 240	0,25/0,5	120 to 0 or 120 to 240	90004
240	0, 5	0 to 120 or 240 to 120	90011
110	0,6	0 to 110	00107
60	1,2	0 to 60	00007

To be read in conjunction with "Operational notes Variable mains transformers".

APPLICATION

These panel mounting transformers will find their main application in those cases, where inefficient load potentiometers or adjustable series resistors are used. They can also successfully replace tapped transformers in some types of inductive voltage control.

DESCRIPTION

The transformers are moulded in reinforced polyester resin. The construction is rugged and professional; the winding is protected by the moulding. The mounting is simple by means of a nut on a threaded bushing.


Soldering tags are provided for the connecting leads.

The coils of the 240~V types are wound in two layers. The outer layer forms the brush track, so that the brush sweeps half the total winding.



ELECTRICAL DATA

Circuit diagram



Input voltage K to N *
Output voltage, no load, T to N 1
Nominal output current over the whole control range
Maximum output current 2)
Voltage per turn of winding
Voltage drop at nominal output current 3)
Losses, no load
Permissible temperature rise at any point ⁴)

2422 530	
00007	00107
60 V +10%	110 V +10%
0 (+2) to 60 (-2) V	0 (+3) to 110 (-3) V
1,2 A	0,6 A
1,32 A	0,7 A
0,122 V	0, 12 V
≤ 6 V	≤ 10 V
≤1,1 W	≤ 1,8 W

max. 70 °C

^{*} Second letter denotes the common input/output terminal.

¹⁾ The output voltage is stated for clockwise rotation when the transformer is mounted behind a panel.


²) See "Operational notes" paragraph "Continuous overload".

³⁾ See "Operational notes" paragraph "Voltage drop".

⁴) See "Operational notes" paragraph "Derating for higher ambient temperatures".

 $^{^{5}}$) 0, 25 A/0, 28 A for input connection between terminals Z and N.






	The state of the s	2422 530		
	00407	90011	90004	
Input voltage N to K *	240 V + 10%	240 V +10%	240 V +10%	
Output voltage, no load, T to K 1	120 (±2) to 0 (+3) V	240(-3) to 120 (±2) V	120 (±2) to 0 (+3) V	
Input voltage K to N	240 V + 10%	240 V +10%	240 V·+10%	
Output voltage, no load, T to N 1	120 (±2) to 240 (-3) V	0 (+3) to 120 (±2) V	120 (±2) to 240 (-3) V	
Input voltage Z to N			120 V +10%	
Output voltage, no load, T to N 1)		120 (±2) to 240 (-3) V	
Input voltage Z to K			120 V +10%	
Output voltage, no load, T to K 1)		120(±2) to 0 (+3) V	
Nominal output current over the whole control range	0,5 A	0,5 A	0,5 A (0,25 A ⁵))	
_	(c) 0,55 A	0,55 A	0,55 A (0,28 A ⁵))	
Voltage per turn of winding	Control of the Contro	0,1	33 V	
Voltage drop at nom. output curre	nt ³)	≤ 2	0 V	
Losses, no load		≤ 1	, 8 W	
Permissible temperature rise at a	ny point ⁴)	ma	x. 70 °C	

Notes see preceding page.

MECHANICAL DATA

Dimensions in mm



Degree of protection (IEC 144)

IP00

Mass

≈700 g

Operating torque

0,03 to 0,07 Nm


Permissible end stop torque

max. 1 Nm

Mounting

Mounting position: any.

The transformers can be fitted to a panel or a chassis (maximum thickness 6 mm) by means of the nut on the threaded bushing. The mounting hole pattern is given in the figure below.



Carbon brushes

Spare carbon brushes, already mounted in the contact arm, can be supplied under catalogue number 4322 027 78660 (or service number 5322 362 40038).

ACCESSORIES

Available accessories:

Control knob and dial See Handbook section "Accessories".

Further information on request.

VARIABLE MAINS TRANSFORMERS moulded type; transformer size code E2

QUICK REFERENCE DATA			
input voltage (V)	output current (A)	output voltage (V)	catalogue number 2422 530
220/240 220 115/130 115 42	0,7 0,83 1,2 1,4 4	0 to 240 0 to 220 0 to 130 0 to 115 0 to 42	01407 11407 01607 11607 90031

To be read in conjunction with "Operational Notes Variable Mains Transformers".

APPLICATION

These panel mounting transformers will find their main application in those cases, where inefficient load potentiometers or adjustable series resistors are used. They can also successfully replace tapped transformers in some types of inductive voltage control.

DESCRIPTION

The transformers are moulded in reinforced polyester resin. The construction is rugged and professional: the winding is protected by the moulding.

The mounting hole pattern is simple, the support area is relatively wide and therefore the transformers can be mounted on thin chassis or panels.


The fixed-length spindle protrudes at both sides: the amount of side-to-side protrusion is adjustable. The spindle can be easily replaced by one of another length.


Screw terminals are provided for the connecting leads.

December 1976 | E2-1

ELECTRICAL DATA

Circuit diagram





2422 530 11407 2422 530 11607 2422 530 90031

Input voltage M to K *
N to K

Output voltage, no load, T to K 1)

Nominal output current over the whole control range

Maximum output current 2)

Voltage per turn of winding

Voltage drop at nom. output current 3)

Losses, no-load

Permissible temperature rise at any point 4)

2422 530				
01407 11407		90031		
220 V +10% 240 V +10%	220 V +10%	42 V +10%		
0 (+3) to 240 (-3 V)	0 (+3) to 220 (-3) V	0 (+1) to 42 (-1) V		
-				
0,7 A	0, 83 A	4 A		
0,83 A	1 A	4,8 A		
0,242 V	0, 23 V	0, 206 V		
≤16 V	≤13 V	≤2 V		
≤4 W	≤4 W	≤2 W		

max. 70 °C



^{*} Second letter denotes the common input/output terminal.

¹⁾ The output voltage is stated for clockwise rotation when the transformer is mounted behind a panel.

²⁾ See "Operational notes" paragraph "Continuous overload".

³⁾ See "Operational notes" paragraph "Voltage drop".

⁴⁾ See "Operational notes" paragraph "Derating for higher ambient temperatures".


Input voltage M to K * N to K
Output voltage, no load, T to K $^{\rm l}$)
Nominal output current over the whole control range
Maximum output current ²)
Voltage per turn of winding
Voltage drop at nominal output current ³)
Losses, no load
Permissible temperature rise at any point 4

2422	530
01607	11607
115 V +10% 130 V +10%	115 V +10%
0 (+2) to 130 (-2) V	0 (+2) to 115 (-2) V
1,2 A	1,4 A
1,4 A	1,7 A
0,211 V	0, 186 V
≤7 V	≤6 V
≤4 W	≤4 W

max. 70 °C



MECHANICAL DATA



¹⁾ for 2422 530 01407 and 0160° ²¹ 105 for 2422 530 90031

3) 37 for 2422 530 90031

*for 2422 530 90031:95 mm

Degree of protection (IEC 144)

IP00

Mass

1250 g

Operating torque

0,05 to 0,1 Nm

Permissible end stop torque


max. 1 Nm

Mounting

Mounting position: any

The transformers can be fitted to a panel or a chassis by means of 2 screws M4 (maximum length = panel thickness +7 mm).

The mounting hole pattern is given in the figure below.



Carbon brushes

Spare carbon brushes, already mounted in the contact arm, can be supplied under catalogue number 4322 026 16310 (or service number 5322 362 40054).

For 2422 530 90031: 4322 027 78720 (or service number 5322 362 44015).

ACCESSORIES

Available accessories:

Control knobs.

Ganging units.

Motor drive modules.

See Handbook section "Accessories" use size code E2

A.C. stabilizer module. at selecting accessories.

Further information on request.



VARIABLE MAINS TRANSFORMERS moulded type; transformer size code E3

QUICK REFERENCE DATA			
input voltage	output current (A)	output voltage	catalogue number
(V)		(V)	2422 530
220/260	1,2	0 to 260	08407
220	1,4	0 to 220	18407

To be read in conjunction with "Operational notes Variable mains transformers".

APPLICATION

These panel mounting transformers are used as power or voltage controls in mass produced apparatus, such as air heaters, ventilator controls, etc.

DESCRIPTION

The transformers are moulded in reinforced polyester resin. The construction is rugged and professional; the winding is protected by the moulding.


The mounting hole pattern is simple, the support area is relatively wide and therefore the transformers can be mounted on thin chassis or panels.


The fixed-length spindle protrudes at both sides: the amount of side-to-side protrusion is adjustable. The spindle can be easily replaced by one of another length. Screw terminals are provided for connecting the leads.



ELECTRICAL DATA

Circuit diagram





0 08407 2422 530 18407

2422 530	
08407	18407
220 V +10% 260 V +10%	220 V +10
0 (+3) to 260 (-3) V	0 (+3) to 220 (-3) V
1,2 A	1,4 A
1,4 A	1,7 A
0,36 V	0,36 V
≤13 V	≤14 V
≤6 W	≤5 W

max. 70 °C

•

Input voltage M to K * N to K

Output voltage T to K 1)

Nominal output current over the whole control range

Maximum output current 2)

Voltage per turn of winding

Voltage drop at nominal output current 3)

Losses, no load

Permissible temperature rise at any point 4)

^{*} Second letter denotes the common input/output terminal.

¹⁾ The output voltage is stated for clockwise rotation when the transformer is mounted behind a panel.


²) See "Operational notes" paragraph "Continuous overload".

³⁾ See "Operational notes" paragraph "Voltage drop".

⁴⁾ See "Operational notes" paragraph "Derating for higher ambient temperatures".

MECHANICAL DATA

Dimensions in mm



Degree of protection (IEC144)

IP00

Mass

≈ 1800 g

Operating torque

0,03 to 0,07 Nm

Permissible end stop torque


1 Nm

Mounting

Mounting position: any

The transformers can be fitted to a panel or a chassis by means of 2 screws M4 (maximum length \approx panel thickness +7 mm).

The mounting hole pattern is given in the figure below.



Carbon brushes

Spare carbon brushes, already mounted in the contact arm, can be supplied under catalogue number 4322 026 16310 (or service number 5322 362 40054).

ACCESSORIES

Available accessories:

Control knobs.

Ganging units.

See Handbook section "Accessories".

Motor drive module.

Use size code E3 at selecting accessories.

A.C. stabilizer module.

Further information on request.



VARIABLE MAINS TRANSFORMERS moulded type; transformer size code E4

	QUICK REFER	RENCE DATA	
input voltage	output current (A)	output voltage	catalogue number
(V)		(V)	2422 530
220/260	2	0 to 260	03407
240/260	2	0 to 260	03507
220	2,5	0 to 220	13407

To be read in conjunction with "Operational notes Variable mains transformers".

APPLICATION

These panel mounting transformers are used as power or voltage controls in mass produced apparatus, such as air heaters, ventilator controls, etc.

DESCRIPTION


The transformers are moulded in reinforced polyester resin. The construction is rugged and professional; the winding is protected by the moulding.

The mounting hole pattern is simple, the support area is relatively wide and therefore the transformers can be mounted on thin chassis or panels.


The fixed-length spindle protrudes at both sides: the amount of side-to-side protrusion is adjustable. The spindle can easily be replaced by one of another length. Screw terminals are provided for connecting the leads.

ELECTRICAL DATA

Circuit diagram



2422 530 03407 and 2422 530 03507



2422 530 13407

Input voltage M to K * N to K
Output voltage, no load, T to K 1)
Nominal output current over the whole control range
Maximum output current ²)
Voltage per turn of winding
Voltage drop at nominal output current 3)
Losses no load

Permissible temperature rise at any point 4)

2422 530					
03407	03507	13407			
220 V +10% 260 V +10%	240 V +10% 260 V +10%	220 V +10%			
0 (+3) to 260 (-3) V	0 (+3) to 260 (-3) V	0 (+3) to 220 (-3) V			
2 A	2 A	2,5 A			
2,4 A	2,4 A	3 A			
0,488 V	0, 488 V	0,478 V			
≤7 V	≤7 V	≤7 V			
	≤8 W				
	70 °C				

^{*} Second letter denotes the common input/output terminal.

¹⁾ The output voltage is stated for clockwise rotation when the transformer is mounted behind a panel.

²⁾ See "Operational notes" paragraph "Continuous overload".


³⁾ See "Operational notes" paragraph "Voltage drop".

⁴⁾ See "Operational notes" paragraph "Derating for higher ambient temperatures".

.

MECHANICAL DATA

Dimensions in mm



Degree of protection

IP00

Mass

≈ 3100 g

Operating torque

0,05 to 0,1 Nm

Permissible end stop torque


1 Nm

Mounting

Mounting position: any

The transformers can be fitted to a panel or a chassis by means of 3 screws M4 (maximum length = panel thickness +7 mm).

The mounting hole pattern is given in the figure below.



Carbon brushes

Spare carbon brushes, already mounted in the contact arm, can be supplied under catalogue number 4322 026 65540 (or service number 5322 362 40079).

ACCESSORIES

Available accessories:

Control knobs.

Ganging units.

See Handbook section "Accessories".

Motor drive module,

Use size code E4 at selecting accessories.

A.C. stabilizer module.

Further information on request.



VARIABLE MAINS TRANSFORMERS moulded type; transformer size code E5

QUICK REFERENCE DATA					
input voltage (V)	output current (A)	output voltage (V)	catalogue number 2422 530		
220 220	4 4	110 to 220 0 to 220	90023 90024		

To be read in conjunction with "Operational notes Variable mains transformers".

APPLICATION

These panel mounting transformers are designed to be built in laboratory, industrial and professional equipment.

DESCRIPTION

The transformers are partly moulded in reinforced polyester resin. The construction is simple but rugged; the impregnated winding is unprotected.


The transformers do not require maintenance.

Screw terminals are provided for the connecting leads.

The mounting hole pattern is simple, the support area is relatively wide and therefore the transformers can be mounted on thin chassis or panels. The transformers are supplied without knob or dial.

ELECTRICAL DATA

Circuit diagram



2422 530				
90023	90024			
220 V +10 % 110 (±3) to 220 (-3) V 80 (±3) V	220 V +10% 0 (+3) to 220 (-3) V 80 (±3) V			

Input voltage N to K *

Output voltage, no load, T to K

M to K

Nominal output current over the whole control range

Maximum output current ²)

Voltage per turn of winding

Voltage drop at nominal output current ³)

Losses, no load

Permissible temperature rise at any point ⁴)

4 A 4,8 A 0,61 V ≤8,1 V ≤6,5 W 70 °C



^{*} Second letter denotes the common input/output terminal.

¹⁾ The output voltage is stated for clockwise rotation when the transformer is mounted behind a panel.


²⁾ See "Operational notes" paragraph "Continuous overload".

³⁾ See "Operational notes" paragraph "Voltage drop".

⁴⁾ See "Operational notes" paragraph "Derating for higher ambient temperatures".

MECHANICAL DATA

Dimensions in mm



Degree of protection (IEC 144)

Mass

Operating torque

Permissible end stop torque

Total angle of rotation, 2422 530 90023


2422 530 90024


Mounting

Mounting position: any

The transformer can be fitted to a panel or a chassis by means of 3 M4 screws (maximum length = panel thickness + 9 mm).

The mounting hole pattern is shown in the drawing.





VARIABLE MAINS TRANSFORMERS

Carbon brushes

Spare carbon brushes can be supplied under catalogue number $4322\ 028\ 01821$ (service number $5322\ 362\ 44017$).

ACCESSORIES

Available accessories:
Ganging units.
Motor drive module,
A.C. stabilizer module.
Further information on request.



VARIABLE MAINS TRANSFORMERS moulded type; transformer size code E6

	QUICK	REFERENCE DATA		
input voltage output current output voltage catalogue number (V) (A) (V) 2422 530				
220/240/276	4,5	0 to 253 or 0 to 276	90028	

To be read in conjunction with "Operational notes Variable mains transformers".

APPLICATION

This panel mounting transformer is designed for use in laboratories and in industrial and professional equipment.

DESCRIPTION

This transformer is partly moulded in reinforced polyester resin. The construction is simple but rugged; the impregnated winding is unprotected.

The transformer does not require maintenance.

Screw terminals are provided for connecting the leads.


The mounting hole pattern is simple, the support area is relatively wide and therefore the transformers can be mounted on thin chassis or panels.

The fixed-length spindle protrudes at both sides; the amount of side-to-side protrusion is adjustable. The spindle can be easily replaced by one of another length.



ELECTRICAL DATA

Circuit diagram



2422	530	90028

Input voltage M to K *		220 V
Output voltage T to K	1)	0 (+3) to 253 (-3) V
Input voltage M to K		240 V
Output voltage T to K	1)	0 (+3,3) to 276 (-3,3) V
Input voltage N to K		276 V
Output voltage T to K	¹)	0 (+3,3) to 276 (-3,3) V
Nominal output current over the whole control range		4, 5 A
Maximum output current	2)	5 A
Voltage per turn of winding input 220 V input 240 V		0, 56 V 0, 61 V
Voltage drop at nominal output current	3)	≤ 6 V
Losses, no load (input voltage M to $K=22$	20 V)	≤ 8 W
Permissible temperature rise at any point	4)	70 °C

^{*}Second letter denotes the common input/output terminal.



¹⁾ The output voltage is stated for clockwise rotation when the transformer is mounted behind a panel.


²⁾ See "Operational notes" paragraph "Continuous overload".


 $^{^{3}}$) See "Operational notes" paragraph "Voltage drop".

⁴⁾ See "Operational notes" paragraph "Derating for higher ambient temperatures".

MECHANICAL DATA

Dimensions in mm





IP00

≈4,5 kg

0,05 to 0,15 Nm

max. 1 Nm

Degree of protection (IEC144)

Mass

Operating torque


Permissible end stop torque

Mounting

Mounting position: any.

The transformer can be fitted to a panel or chassis by means of 3 screws M4 (maximum length = panel thickness \pm 10 mm).

The mounting hole pattern is in accordance with DIN42595 and shown in the figure.



VARIABLE MAINS TRANSFORMERS

Carbon brushes

Spare carbon brushes can be supplied under catalogue number $4322\ 027\ 75750$ (or service number $5322\ 362\ 44012$).

ACCESSORIES

Available accessories:
Control knobs.
Ganging units.
Chokes for parallel connection.
Motor drive module.

A.C. stabilizer module. Further information on request. See Handbook section "Accessories". Use size code E6 at selecting accessories.



VARIABLE MAINS TRANSFORMERS moulded type; transformer size code E8

QUICK REFERENCE DATA					
input voltage	output current (A)	output voltage	catalogue number		
(V)		(V)	2422 530		
220/260	12	0 to 260	06407		
240/260	12	0 to 260	06507		
220	15	0 to 220	16407		

To be read in conjunction with "Operational notes Variable mains transformers".

APPLICATION

These panel mounting transformers have been developed to meet the demand for larger power requirements e.g. power plants, studios, cinemas, etc.

DESCRIPTION


The annular core with a single layer of insulated copper wire is moulded in a reinforced polyester resin bottom part. The contact surface is on the cylindrical outside and it has a special metal finish to ensure permanently perfect contact and to prevent any oxidation by overheating.

The fixed-length spindle protrudes at both sides: the amount of side-to-side protrusion is adjustable. The spindle can easily be replaced by one of another length. Screw terminals are provided for connecting the leads.



ELECTRICAL DATA

Circuit diagram



2422 530 06407 2422 530 06507 KL = MN

Input voltage L to N *
K to N

Output voltage, no load, T to N^{-1})

Nominal output current over the whole control range


Maximum output current

Voltage per turn of winding

Voltage drop at nominal output current 3)

Losses, no load

Permissible temperature rise at any point 4)



2422 531 16407

2422 530						
06507	16407					
240 V + 10% 260 V + 10%	220 V + 10%					
0 to 260 (+3) V	0 to 260 (+3) V					
12 A	15 A					
15 A	18 A					
0,75 V	0,75 V					
≤ 6 V	≤ 4,5 V					
	06507 240 V + 10% 260 V + 10% 0 to 260 (+3) V 12 A 15 A 0, 75 V					

 $\leq 19, 5 \text{ W}$

max. 90 °C



Second letter denotes the common input/output terminal.

¹⁾ The output voltage is stated for clockwise rotation when the transformer is mounted behind a panel.


²⁾ See "Operational notes" paragraph "Continuous overload".

³⁾ See "Operational notes" paragraph "Voltage drop".

⁴⁾ See "Operational notes" paragraph "Derating for higher ambient temperatures".

MECHANICAL DATA

Dimensions in mm



Degree of protection (IEC144)

Mass

Operating torque

Permissible end stop torque

IP00

 $\approx 10 \text{ kg}$

0, 25 to 0, 5 Nm


max. 4 Nm

Mounting

Mounting position: any.

The transformers can be fitted to a panel or chassis by means of 3 screws M6 (maximum length = panel thickness + 10 mm).

The mounting hole pattern is given in the figure. 3 Holes on the outer circle or on the inner circle are sufficient for mounting.



VARIABLE MAINS TRANSFORMERS

Carbon brushes

Spare carbon brushes can be supplied under catalogue number $4322\ 028\ 01801$ (service number $5322\ 362\ 44016$).

For older transformers with a dimension A = 102 mm -see drawing- the catalogue number of the carbon brushes is 4322 027 54810 (service number 5322 362 40096).

ACCESSORIES

Available accessories:

Control knobs.
Ganging units.
Chokes for parallel connection'
Motor drive module.
A.C. stabilizer module.
Further information on request.

See Handbook section "Accessories" Use size code E8 at selecting accessories.



VARIABLE MAINS TRANSFORMERS moulded type; transformer size code E10

QUICK REFERENCE DATA					
input voltage (V)	output current (A)	output voltage (V)	catalogue 2422 530		
			bench model	panel model	
220/260 240/260	23A 23A	0 to 260 0 to 260	07411 07511	07407 07507	

To be read in conjunction with "Operational notes Variable mains transformers".

APPLICATION

These panel mounting or bench model transformers have been designed for industrial use e.g. cinemas, studios, power plants etc.

DESCRIPTION

The transformers are partly moulded in reinforced polyester resin.

The construction is simple but rugged.

The transformers need no maintenance.


Screw terminals are provided for connecting the leads.

The fixed-length spindle protrudes at both sides; the amount of side-to-side protrusion is adjustable. The spindle can be easily replaced by one of another length.




ELECTRICAL DATA

Circuit diagrams



KL = MN
Z = centre_tap

¹)



07411	07511
07407	07507
220 V + 10%	240 V + 10%
. 260 N	7 + 10%
0 to 2	260 (+3) V
23 A	
30 A	
0,9 V	7
≤ 6 V	
≤ 40	W

90 °C

2422 530



1			0	K	to N	1				
Outp	ut	vol	tage	€,	no l	load	, Т	c to	o N	Į
3. 7		, ,								

Input voltage L to N*

Nominal output current over the whole control range

Maximum output current 2)

 $Voltage\ per\ turn\ of\ winding$

Voltage drop at nominal output current 3)

Losses, no load

Permissible temperature rise at any point ⁴)

^{*} Second letter denotes the common input/output terminal.


The output voltage is stated for clockwise rotation when the transformer is mounted behind a panel.


²⁾ See "Operational notes" paragraph "Continuous overload".

³⁾ See "Operational notes" paragraph "Voltage drop".

⁴⁾ See "Operational notes" paragraph "Derating for higher ambient temperatures".


MECHANICAL DATA






K L Z T M N 7775161

2422 530 07407 07507





 $\begin{array}{c} 2422\ 530\ 07411 \\ 07511 \end{array}$

Degree of protection (IEC144)
Mass
Operating torque
Permissible end stop torque

bench model	panel model	
IP20	IP00	
≈19,8 kg	≈17,9 kg	
1 to 1,5 Nm		
max.	5 Nm	

Carbon brushes

Spare carbon brushes can be supplied under catalogue number $4322\ 028\ 01801$ (service number $5322\ 362\ 44016$).


Mounting

Mounting position: any.

The transformers (both panel and bench models) can be fitted to a panel or chassis by means of 4 screws M8 (maximum length = panel thickness +12 mm).

The mounting hole pattern is shown below.

Remove pads of bench model before mounting.





ACCESSORIES

Available accessories:

Control knobs.
Ganging unit.
Motor drive module.
Chokes for parallel connection.
A.C. stabilizer module.
Further information on request.

See Handbook section "Accessories". Use size code E10 at selecting accessories. Variable mains transformers (separate windings)



VARIABLE MAINS TRANSFORMERS with separate windings; transformer size code C4

	QUIC	K REFERENCE DATA		
input voltage (V)	output current (A)	output voltage (V)	catalogue 2422 529	number
			panel model	lab. model
220	3	0 to 242	00006	00005

APPLICATION

These variable transformers find their main application as isolating transformers in radio and television repair shops and in laboratories.

DESCRIPTION

The annular core with two separated layers of insulated copper wire is insulated from and supported in a cast aluminium frame.

The coil resistance is very low $(3,7 \Omega)$.

The contact surface is on the top of the coil.

The angle of rotation is 320°; end stops prevent the two brushes, which operate in parallel, from overrunning the contact track.

The fixed-length spindle protrudes at both sides; the amount of side-to-side protrusion is adjustable. The spindle can easily be replaced by one of another length.

Screw terminals are provided for connecting the leads.

The laboratory model has a sturdy metal housing with handle and is provided with a cable with a mains plug with side-contact earth, a socket, a fuse, and a voltmeter indicating the output voltage.





TRANSFORMERS SIZE CODE C4

VARIABLE MAINS TRANSFORMERS WITH SEPARATE WINDINGS

ELECTRICAL DATA

Circuit diagram





panel model

laboratory model

Input voltage N to K	220 V + 10%
Output voltage, no load M to T *	0 to ≥ 242 V
Nominal output current over the whole control range	3 A
Short term overload current	5 A
Voltage per turn of winding	0,76 V
Voltage drop at nominal output current	≤ 12 V
Losses, no load	≤ 11 W
Frequency range	50 to 60 Hz
Insulation resistance ²) after damp heat test (IEC 68-2, test Ca, 21 days)	> 5 MΩ
Test voltage for 1 min 2)	2000 V, 50 Hz
Air gap 2)	≥ 4 mm
Leakage path 2)	≥ 5 mm
Ambient temperature range	-10 to +40 °C
Climatic category, IEC 68-1	10/040/21
Maximum temperature rise at any point	70 °C

^{*)} Clockwise rotation of the spindle results in an increasing output voltage when the transformer is mounted behind a panel.




¹⁾ For inductive loads it may be necessary to replace the fuse by one which can stand high transient currents.


²⁾ Between windings and between live and non-live parts.


MECHANICAL DATA

Dimensions in mm



laboratory model





panel model

TRANSFORMERS

VARIABLE MAINS TRANSFORMERS WITH SEPARATE WINDINGS

Degree of protection (IEC 144) panel model

lab. model

Mass, panel model

laboratory model

Operating torque

Permissible end stop torque

Total angle of rotation

Life, guaranteed

Life expectancy

IP00

IP20

≈ 8,5 kg

≈9,6 kg

0, 15 to 0, 3 Nm

max. 4 Nm

320°

 $> 100\,000$ complete rotations

> 250 000 complete rotations

Mounting

Mounting position: any

The transformers can be fitted to a panel or a chassis by means of 3 screws M6 (maximum length = panel thickness + 11 mm).

Carbon brushes

Spare carbon brushes can be supplied under catalogue number 4322 027 75160 (or service number 5322 362 40044). 1)

ACCESSORIES

Available accessories:

Control knobs.

Ganging unit

Motor drive module

See Handbook section

"Accessories".

Use size code C4 at selecting

accessories.

Further information on request

Spare carbon brushes for moulded transformer (previous version) are available under catalogue number 4322 027 55830 (or service number 5322 362 44003).



Accessories





GANGING AND MOTOR DRIVE operational notes

Ganging units are used for the mechanical ganging of two or three variable transformers. They are supplied in an assembly kit. The stacked transformers may be hand or motor driven.

Most transformers, either stacked or individual, can be provided with a remote-controlled motor drive.

Two or three transformers may be mechanically and electrically connected in parallel (electrical ganging).

To prevent high interchange currents, caused by differences in output voltage between the ganged transformers, **chokes** should be inserted between the output terminals of the transformers.

In the following tables the required parts to be ordered - with catalogue number and number of pieces - are given for the various transformer size codes.

Simple motor drive components for various rotational frequencies (rotation times) as well as components for mechanical ganging (hand or motor driven) or electrical ganging may be derived from the tables.

ORDERING

- 1. For mechanical ganging without motor drive order ganging unit and spindle.
- For motor drive order in addition to 1 the components given under the heading "motor drive".
- 3. For electrical ganging order also a parallel choke.

Notes to tables

- ¹) The effective rotation angle of the variable mains transformers is 320° , so the actual rotation time between end stops is $\frac{320}{360}$ x listed rotation time.
- ²) A series of gear-boxes with gear ratio from 25:6 to 15000:1, catalogue number 9904 130 01... is available. With these gear-boxes a pinion set 2422 532 00037 must be ordered.
 - For further information ask your supplier.

Ganging and motor drive transformer size code E2, E3, E4, C1 and C2

Part										-								m	oto	r d	rive				
E2, E3 and E4 1			peg		med	cha	nic	al ç	an	gin	9		or drive		•						syn	chr.	car	ac.	-
E2, E3 and E4 1		ne for 0° 1	transf. u				g	,	spii	ndle	9	 it 0027	t for mot 0058	5:1	25:2	25:1	50:1	100:1	1500:1	3000:1	220 50	O V Hz	330	V a.c.	ndle 8990
E2, E3 and E4 6 s	nsformer code	ation tin	nbers of	-					_	T-		plate k 22 532 0	ging uni 22 532 0	19/					_	321	131	131	8 µF	56 µF	adapter spindle 4322 026 68990
E2, E3 and E4 6 s	trar	rota 1 re		8	8	8	8	199	199	88	86	 			657	657	657	959	399	359		4	0,1	0,0	43, ad
E2, E3 and E4 15 s		6 s	2	1			Ė	1		L			1												1
E2, E3 and E4 The color of t			1	L			L		Ľ													1		1	1
E2, E3 and E4 E2, E3 and E4 E1 min		15 s	3	1	+			-	1			 1	1												1
E2, E3 and E4 1 min		30 s	2	1	+		-	1	1	F		1	1	-		1		_	_		4		4		1 1
and E4 2 min	F0 F0	1 :	1	1				1	Ľ			1	1			-					1		1		1 1
2 min 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 </td <td></td> <td>1 min</td> <td>3</td> <td>Ľ</td> <td>-</td> <td>L</td> <td>-</td> <td>Ľ</td> <td>1</td> <td>=</td> <td></td> <td>1</td> <td>1</td> <td></td> <td></td> <td></td> <td></td> <td>1</td> <td></td> <td></td> <td></td> <td>1</td> <td></td> <td>1</td> <td>1</td>		1 min	3	Ľ	-	L	-	Ľ	1	=		1	1					1				1		1	1
30 min		2 min	2	1	-	F	F	1	1			 1	1					1				1		1	1
The state of the s		30 min	1 2	1				1				1	1					_	1	_		1		1	1 1
C1 and C2 1		1 h	1	1				1				1	1									1		1	1 1
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$			3	F	1	-	L	L	1	_		1	1	_			4			1		1		1	1
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$		6 s	2	I	-	1	1			1	1														
C1 and C2		15 s	1 2			1	E	E	E	1		1	1		1							1		1	
C1 and C2 I min		30 s	1	F	-	1	1	-	-	1	1	1	1	-	1	-					1				
3 1 1 1 1 1 1 1 2 min 2 1 1 1 1 1 1 1 1 1 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			3	1			1		E		1	1	1								1	1	1	1	
2 min 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 <td>C2</td> <td>1 min</td> <td>3</td> <td>-</td> <td></td> <td>1</td> <td>1</td> <td>-</td> <td>F</td> <td>1</td> <td>1</td> <td>1</td> <td>1</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>1</td> <td></td> <td>1</td> <td></td>	C2	1 min	3	-		1	1	-	F	1	1	1	1									1		1	
	-	2 min	2	+	-	1	1	-	-	1	1	1	1					1				1		1	
		30 min	· 1	I	F	1				1		1	1						1			1		1	
3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1h 2 1 1 1 1 1 1 1 1		1 h	1	+	-	1	1	-	F	1	1	1	1	F			+		1			1		1	

 $^{^{1}}$ + 2 = see operational notes "Ganging and motor drive".



													_										
																n	oto	or d	rive				
	ne for 0° 1	number of transf. used	gang		_		ing	conne para cho			gang unit mo dri 8900	for tor ve	5:1	g	ear	box²		3000:1	syn mo 22	ers. chr. otor 0 V Hz	phas cap 330		ndle 3990
transformer size code	rotation time for 1 rev. of 360° ¹	number of	2422 99000	532 9 <u>9</u> 000	\vdash	- т	026 09280 09280	* * * * * * * * *	532	top plate kit 2422 532 00027	2422 532 00058	2422 532 00028	65761	-т		026	Γ	65821	06131	04131	0,18 µF	0,056 µF	adapter spindle 4322 026 68990
	6 s	_1 2 3	1	1	1	1		1	1	1	1	1	1						1		1		1
	15 s	2 3	1	1	1	1		1	1	1 1 1	1	1		1 1 1	1				1	1	1	1	1 1 1
	30 s	1 2 3	1	1	1	1		1	1	1 1 1 1	1	1			1	1			1	1	1	1	1 1 1
E6	1 min	2 3 1	1	1	1	1		1	1	1 1 1	1	1				1 1			1	1	1	1	1 1
	2 min	3	1	1	1	1		1	1	1 1 1	1	1				1	1			1 1 1		1 1 1	1 1
	30 min	2 3 1 2	1	1	1	1		1 1 1	1	1 1 1 1	1	1 1			1		1	1		1 1 1 1		1 1 1 1	1 1 1 1
	1 h	3		1			=	1	1	1	1	1	1		#			1	1	1	1	1	1
	6 s	3	1	1			1 1	1	1	1	1	1	1	1					1	1	1	1	
	15 s	2 3 1	1	1			1 1	1	1	1 1 1	1	1		1	1	-			1	1	1	1	
C3 and C4	30 s	2 3 1	1	1			1 1	1	1	1 1 1	1	1				1			1	î	1	1	
	1 min	3	1	1			1 1	1	1	1 1 1	1	1				1 1			1	1	1	1	
	2 min	3	1	1			1	1	1	1 1 1	1	1		1		1	1			1 1 1		1 1 1	
	30 min	3	1	1			1 1	1	1	1 1 1	1	1			+	#	1	1		1 1 1 1		1 1 1 1	
	1 h	3	1	1			1	1	1	1		1		_		\pm		1		1		1	

^{* = 432253200014} may be replaced by 00013.



 $^{^{1}}$ + 2 = see operational notes "Ganging and motor drive".

ACCESSORIES

Ganging and motor drive transformer size code E8 and E10


														m	oto	or d	riv						
		per	-	gan		cal g	<u>. </u>	ngii		hoke	top k	plate it	gang unit mo	ing for			jea jea	r bo	tio			revers. synchr. motor 990411106131220 V, 50 Hz	
	or 1	ınsf. u	2	42:	2 53	32				rallel o	2422	2 532	dri		5:1	25:2	25:1	50:1	00:1	1500:1	3000:1	motor 1 220	/ a.c.
e mer	time 1 360°	s of tra					cit	8018	8 0 1 8	ing pa			do .	2 000(Ш			22 (L_	_	ĕ	nchr. 10613	capac.
transformer size code	rotation time for 1 rev. of 360° ¹	numbers of transf. used	00039	00041	00063	00064	incl. in kit	4322 028 01850	4322 028 01860	connecting parallel choke 2422 532 00017	00042	00065	incl. in top plate kit.	2422 532 00062	65761	65771	65781	65791	65801	65811	65821	revers. sy 9904 11	phasing capac. 0,18 μF; 330 V a.c.
		1	Ļ	L	L		_			4													
	6 s	2	1	1	├	Н	1		-	1 2						-		-	-	-	\vdash		
		1	+	† '	-				-		1		1		\vdash	1	_	-	-	-	Н	1	1
	15 s	2	1	T	Γ	П	1			1			-			Ė	_			1	П		<u> </u>
		3	L	1			1			2													
		1	Ļ	1	_		_				1		1		Н	4	1		_	_		_1_	1
	30 s	2	1	1	H		1	_	_	1 2	1		1		H	-	1	_	-	_	Н	1	1
•		1	+	+-	+	\vdash	-	-	-		1		1		Н	-		1	-		H	1	1
E8	1 min	2	1	+	\vdash		1		-	1	1		1		Н	1		1	-		H	1	1
		3	Ė	1	T		1	_	-	2	1		1		Н	7		1		-	Н	<u> </u>	1
	2 min	1									1		1		П				1			1	1
	2 min	2	1				1			1	1		1						1			1	1
	2	3	-	1	-	-	1		_	2	1		1			-		_	1			1	1
	30 min	2	î	+-	-	-	1		-	1	1		1			-	-			1	4	1	1
	30 11111	3	+	1	+	\vdash	1		-	2	1		1		Н	-	-	-	-	1	\vdash	1	1
		1	T	Ė	\vdash	П	·				1		1		Н	T		-		÷	1	1	1
	1 h	2	1				1			1	1		1								1	1	1
		3		1			1			2	1		1								1	1	1
			F	=	F	\vdash	_									7			_	_			=
	45 s	2	⊬	╁	1	Н		1	-	1		1		_1_	H	1	-	-	_		-	_1_	1_
	45 \$	3	╁	+-	+	1		-	1	2					Н	-	-	\dashv	-		+		
		1	H	T	\vdash	†			Ė			1		1	Н	7	1	-		-	\dashv	1	1
	90 s	2	T	T	1	П		1		1		1				7	1	7			1	1	1
		3				1			1	2													
		1		L	L			L.,	_			1		_1_				1				1	1
	3 min	2	-	-	1	Ļ		1	_	11		_1_				-	-	1	_	_	4	_1_	1_
E10		3	+-	╀	+	1		_	1	2	-	1			Н	-	-	1	-	-	4	1	1_
	6 min	1 2	╁	╁	1	\vdash		1	-	1		1		_1_	Н	+	-	-	1	-	+	1	1
3			╁	+	†	1		<u> </u>	1	2		1	-		H	+	+	\dashv	1	-		1	1
	1				1		1				-	Ì	1	7	1	1							
	90 min	2	T		1	П		1		1		1			H	7		1		1	7	1	1
	3 1 1 2		2		1								1		1	1							
		1						1		1							1	1	1				
	180 min	2	+	1	1	-		1		1		1				1	4	4	-	-	1	1	1
	L	3	L	_	L	1			1	2		1						$_{\perp}$			1	1	1


 $^{^{1}\,}$ + $^{2}\,$ = see operational notes "Ganging and motor drive".




Dimensions


Transformers with size codes C1, C2, C3, C4, E2, E3, E4, E6









transformer						dimer	sions	(mm)				
size code	A	В	Cmin	D	Е	F	G	Н1	Н2	K	Ll	L2	Т
E2	110	-	120	155	54	93	164	198	180	25	175	190+d	223
E3	110	-	120	155	54	93	164	217	199	25	195	219+d	242
E4	110	-	120	155	54	93	164	229	211	25	205	22 1+d	252
C1	141	-	158	155	54	93	164	282	264	25	270	274+d	313
C2	141	-	158	155	54	93	164	286	268	25	270	276+d	317
C3	141	161	158	212	68	121	214	291	273	29	270	284+d	326
C4	141	176	158	212	68	121	214	294	276	29	270	287+d	329
E6	141	_	158	2 12	68	121	214	265	247	25	255	257+d	300








transformer		dimensions (mm)											
size code	A	В	Cmin	D	Е	F	G	Н1	H ₂	K	L1	L2	T
E2	220	-	229	155	54	93	164	308	290	25	285	300+d	333
E3	220	-	229	155	54	93	164	327	309	25	305	329+d	352
E4	220	-	229	155	54	93	164	339	321	25	315	331+d	362
C1	282	-	299	155	54	93	164	423	405	25	410	415+d	454
C2	282	- T	299	155	54	93	164	427	409	25	410	417+d	458
C3	282	161	299	212	68	121	214	432	414	29	410	425+d	467
$\mathbf{C4}_{i}$	2 82	176	299	2 12	68	.121	214	435	417	29	410	428+d	470
E6	2 82	- a	299	212	68	121	214	406	388	25	396	398+d	441


Note - The supplied spindles (300 mm or 450 mm length) should be shortened to the required length L1 or L2.





=


Transformers with size code E8
















Transformers with size code E10












ELECTRICAL GANGING

Parallel ganging


Two or three variable mains transformers can be ganged in parallel for the supply of higher single-phase secondary currents.

Chokes must be used to prevent high interchange currents between the parallel-connected circuits.

Transformers with size code E6,C3 and C4




Two transformers connected in parallel




Three transformers connected in parallel

Transformers with size code E8 and E10



Two transformers connected in parallel




Three transformers connected in parallel



Series ganging

Two variable mains transformers can be ganged in series for connection of high input voltages (max. 520 V).

The two brushes move simultaneously toward, or away from, the line terminals of the transformers, which means that the load is "floating".




Two transformers connected in series

Three-phase ganging

Three transformers in 从 circuit

To control three-phase voltages, three transformers can be connected in star.




Three transformers connected in 战 circuit

Two transformers in open Δ circuit

Voltage control of the three-phase mains can also be obtained by using two variable transformers, connected in "open delta".

The circuit applies to $127/220\,\mathrm{V}$ mains for transformers with 220 V input. This circuit provides full control without phase shift.




Two transformers connected in open Δ circuit



Chokes

For parallel connection of two or three transformers, chokes must be inserted between the output terminals to prevent high interchange currents caused by differences in ganging. The permissible output voltage difference between the ganged transformers is ≤ 2 V.

The following chokes are available:



Catalogue number 2422 532 00017


MOTOR DRIVE MODULES

Some transformers, either stacked or individual, can be provided with a remote-controlled motor drive module.

A motor drive module consists of the following parts:

- reversible synchronous motor
- phasing capacitor
- gear box
- ganging unit for the motor drive
- top plate with connecting block, switches and auxiliary parts (supplied in assembly kit). Instructions for use are packed with the kit for assembling the top plate.

The main dimensions are given in the figures below.




Transformer size codes E2,E3,E4,E6,E8 and C1 to C4 inclusive.

a = 75 mm, if motor 9904 111 06131 is used = 25 mm, if motor 9904 111 04131 is used

If 2 or 3 ganged transformers are used add table dimension (mm) to the height given in the Figure.

transformer size	2 transformers	3 transformers
C1,C2,C3,C4 E6,E8	141	282
E2, E3, E4	110	220
E10	170	340

Transformer size code E10



Further dimensions see under "Mechanical ganging".

The synchronous motors are 220 V, 50 Hz.

Motors for other voltages and frequencies: contact your supplier.



=

A.C. STABILIZER MODULE 2422 532 00061

QUICK REFERENCE DATA										
Input voltage	220 V, +10%, -15%; 50 Hz									
Stabilized output voltage of the controlled transformer	5 to 115% of input voltage									
Maximum stabilization accuracy	±0,5 V									
Ambient temperature range	-10 to +45 °C									

APPLICATION

This automatic stabilizer module can be used in combination with motor driven transformers for correction of voltage variations. Its main use will be in those applications where the speed of response is of secondary importance to waveform distortion, and where the price per kVA of controlled power must be kept low. Examples of areas of application are test and research laboratories, service shops, and factories with complex machinery. The module can also be used as a voltage, light or temperature-sensitive control for different power sources.

DESCRIPTION

A complete a.c. stabilizer circuit consists of:

- one or more mains transformers
- a transformer ganging unit, if two or three transformers are used
- a motor drive module with 220 V reversible synchronous motor, see chapter "Motor drive modules"
- the a.c. stabilizer module
- a control potentiometer

The stabilizer circuit is shown in Fig. 1 in block diagram form. A stabilized power supply provides a d.c. reference voltage $(V_{\text{ref}}),$ which is applied to the control potentiometer. This potentiometer reduces the reference voltage by a factor $k_1,$ thus the voltage k_1V_{ref} is applied to the comparator. The output voltage of the variable mains transformer is applied to the primary of a step-down transformer whose secondary output is rectified. The output of the rectifier, $k_2\ V_{\text{out}},$ is applied to the other comparator input. The comparator provides an output e to the switching amplifier when the difference between $k_2\ V_{\text{out}}$ and $k_1\ V_{\text{ref}}$ exceeds the value set by the accuracy potentiometer on the module. The output of the switching amplifier energizes the appropriate relay for driving the motor in the direction which corrects the voltage variation of the transformer.

The accuracy potentiometer (see Fig. 2) adjusts the stabilization accuracy between $\pm 0.5 \, \mathrm{V}$ and $\pm 2.5 \, \mathrm{V}$; correct adjustment is necessary to prevent the system hunting. The system has a tendency to hunt because the rotor of a synchronous motor has permanent magnets and cannot stop between pole pairs, and also because the movement of the transformer brush from winding to winding causes a stepping voltage. A coincidence of these conditions can exceed the accuracy potentiometer setting causing the stabilizer to hunt for the accurate transformer brush position, therefore the accuracy potentiometer would need re-adjustment. The phenomenon is dependent on control speed, i.e. the total gear ratio between motor and transformer drive spindle, thus a high control speed must be combined with a large voltage tolerance.





Fig. 1



ACCESSORIES

MECHANICAL DATA

Dimensions in mm






Fig. 2

Weight: approx. 700 g Housing: lacquered metal

Connections are made via two screw-terminal blocks.

ELECTRICAL DATA

Terminals 1 and 2

Input voltage 220 V, +10%, -15%; 50 Hz

Power consumption, relays not operating 2,5 W

relays operating 3 W

Terminals 2 and 3

Voltage to be stabilized 0 to 260 Va.c.

Impedance $5 \text{ k}\Omega$

Terminals 1 and 4

and 1 and 8

Maximum switching capability of relays 250 Va.c., 1 A, $\cos \varphi = 0.7$

Terminals 5(+) and 7(-)

Terminals 6(+) and 7(-)

Reference output voltage $+12~\mathrm{V\,d.\,c.}$ Maximum load $5~\mathrm{mA}$

Manifestal 1000

Reference input voltage 0 to + 12 Vd.c.

Maximum current consumption 1 mA

Stabilized output voltage transformers 220 V/0-220 V transformers 220 V/0-260 V

Accuracy

adjustable between 5 and 100% of input voltage adjustable between 5 and 115% of input voltage

adjustable with accuracy potentiometer between ± 0.5 Va.c. or voltage per turn of winding, whichever is the higher, 1) and ± 2.5 Va.c.

Maximum control speed 23 A transformers other transformers

Operating temperature range


Storage temperature range

 $6,5 \text{ V/s}^2$) 50 V/s 2)

-10 to +45 °C

 $-25 \text{ to} + 85 \text{ }^{\circ}\text{C}$


Connections



- 1) Valid for gear ratios > 10.1, see Tables 2 and 3 of chapter "Motor drive modules".
- 2) Provided the motor and gearbox are selected from Tables 2 and 3 of chapter "Motor drive modules".







- Notes Connections to terminals 1 and 5 of the motor drive module may require interchanging to produce correct direction of rotation (depends on type of gear box used).
 - The recommended value of the control potentiometer is 5 kΩ, $\pm 20\%$, 0,25 W.
 - If only stabilization or positioning at a lower voltage than the input voltage is required the phase can be connected to N in stead of M.
 - For the value of the phasing capacitor, see chapter "Motor drive modules".

APPLICATION INFORMATION

Heavy load application

Stabilizing a heavy load so that it is independent of input or total load current variations can be achieved by a boost transformer connected in series with the variable transformer. The permissible load is thus increased by the boost ratio factor. For example, with an input voltage of 220 V, an 8,5 A variable transformer can supply 0 to 110 V to a 5:1 ratio boost transformer thus controlling 42,5 A over 22 V.




Fig. 4

ACCESSORIES

VARIABLE MAINS TRANSFORMERS

Programmed stabilization

An external programmed voltage source can be injected into the stabilizer module. This can be done by connecting a control voltage ($V_{control}$) of max. 12 V to terminals 6(+) and 7(-); terminal 5 is not used. Then the stabilized output voltage is: $V_{output} = k$. $V_{control}$, in which $k = 23 \pm 7\%$.

Temperature and illumination level control

Instead of a control potentiometer a combination of fixed resistors and NTC thermistors or LDRs can be used to control a temperature or illumination level respectively.



CONTROL KNOBS

A selection of combined control knob and dial accessories is listed below. These items are intended for **panel model** transformers, to enable ease of adjustment and to provide a visual setting indication.

Choice of control knob is determined by the spindle diameter and output voltage range of the transformer. The selection includes large diameter dials which allows panel screws to be concealed.

All control knobs have a clamping collet enabling them to be locked in any position on the spindle,


dial calibration	d	D1	D2	catalogue number	intended for transformer
	(mm)	1	{	000000000000000000000000000000000000000	size code
0 - 260 V	6	60	78	2922 511 90043	
0 - 115 %	6	60	78	90044	E1, E2, E3, E4, E6
0 - 270 V	6	60	78	90045	E1, E2, E3, E4, E0
0 - 100 %	6	60	78	90046)
0 - 100 %	8	60	78	2922 511 90047	
0 - 115 %	8	60	78	90048	G1 G2
0 - 260 V	8	60	78	90049	C1, C2
0 - 270 V	8	60	78	90051	J
0 - 100 %	8	80	106	2922 511 90052	
0 - 115 %	8	80	106	90053	
0 - 260 V	8	80	106	90054	
0 - 270 V	8	80	106	90055	C3, C4, E8
0 - 100 %	8	80	125	2922 511 90056	
0 - 115 %	8	80	125	90057	
0 - 260 V	8	80	125	90058	,
0 - 270 V	8	80	125	90059	
	i l			1	1

The control knob and dial for E10 size transformers are separate items (the dial must be fitted onto the panel):

- knob: D1 = 100 mm,

d = 10 mm, 19 mm deep cat.no. 2922 511 90028

- dial: calibration 0-260 V, D2 = 155 mm cat.no. 4322 026 18560



E10



CONTENTS

SURVEY VARIABLE MAINS TRANSFORMERS

Catalogue no.	See under size code	Catalogue no.	See under size code
2422 529 00005 00006	C4 1) C4 1)	2422 530 05405 05406 05501	C4 C4
2422 530 00007 00107 00407 01407 01607	E1 E1 E1 E2 E2	05506 06407 06507 07407	C4 C4 E8 E8 E10
02306 02401 02406 02501 02506	C1 C1 C1 C1 C1	07411 07507 07511 08407 11407	E10 E10 E10 E3 E2 2)
03306 03401 03405 03406 03407	C2 C2 C2 C2 C2 E4	11607 13407 15406 16407 18407	E2 E4 C4 E8 E3
03501 03506 03507 04306 04401	C2 C2 E4 C3 C3	90004 90011 90023 90024 90028	E1 E1 E5 E5 E6
04405 04406 04501 04506 05401	C3 C3 C3 C3 C3 C4	90031	E2)

ACCESSORIES

Operational notes Mechanical ganging units Motor drive modules Electrical ganging (chokes) Control knobs

A.C. stabilizer module

¹⁾ Section "Variable mains transformers with separate windings".

²⁾ Section "Variable mains transformers auto-transformers".

Variable mains transformers (auto-transformers)
Variable mains transformers (separate windings)
Accessories
Contents

Electronic components and materials for professional, industrial and consumer uses from the world-wide Philips Group of Companies

Argentina: FAPESA I.y.C., Av. Crovara 2550, Tablada, Prov. de BUENOS AIRES, Tel. 652-7438/7478.

Australia: PHILIPS INDUSTRIES HOLDINGS LTD., Elcoma Division, 67 Mars Road, LANE COVE, 2066, N.S.W., Tel. 42 1261.

Austria: ÖSTERREICHISCHE PHILIPS BAUELEMENTE Industrie G.m.b.H., Triester Str. 64, A-1101 WIEN, Tel. 62 91 11.

Belgium: M.B.L.E., 80, rue des Deux Gares, B-1070 BRUXELLES, Tel 523 00 00.

Brazil: IBRAPE, Caixa Postal 7383, Av. Paulista 2073-S/Loja, SAO PAULO, SP, Tel. 287-7144.

Canada: PHILIPS ELECTRONICS LTD., Electron Devices Div., 601 Milner Ave., SCARBOROUGH, Ontario, M1B 1M8, Tel. 292-5161.

Chile: PHILIPS CHILENA S.A., Av. Santa Maria 0760, SANTIAGO, Tel. 39-40 01.

Colombia: SADAPE S.A., P.O. Box 9805 Calle 13, No. 51 + 39, BOGOTA D.E. 1., Tel. 600 600.

Denmark: MINIWATT A/S, Emdrupvej 115A, DK-2400 KØBENHAVN NV., Tel. (01) 69 16 22.
Finland: OY PHILIPS AB, Elcoma Division. Kaivokatu 8, SF-00100 HELSINKI 10, Tel. 1 72 71.

France: R.T.C. LA RADIOTECHNIQUE-COMPELEC, 130 Avenue Ledru Rollin, F-75540 PARIS 11, Tel. 355-44-99.

Germany: VALVO, UB Bauelemente der Philips G.m.b.H., Valvo Haus, Burchardstrasse 19, D-2 HAMBURG 1, Tel. (040) 3296-1.

Greece: PHILIPS S.A. HELLENIQUE, Elcoma Division, 52, Av. Syngrou, ATHENS, Tel. 915 311.

Hong Kong: PHILIPS HONG KONG LTD., Comp. Dept., Philips Ind. Bldg., Kung Yip St., K.C.T.L. 289, KWAI SHUNG, N.T. Tel. 12-24 51 21.

India: PHILIPS INDIA LTD., Elcoma Div., Band Box House, 254-D, Dr. Annie Besant Rd., Prabhadevi, BOMBAY-25-DD, Tel. 457 311-5.

Indonesia: P.T. PHILIPS-RALIN ELECTRONICS, Elcoma Division, 'Timah' Building, Jl. Jen. Gatot Subroto, JAKARTA, Tel. 44 163.

Ireland: PHILIPS ELECTRICAL (IRELAND) LTD., Newstead, Clonskeagh, DUBLIN 14, Tel. 69 33 55.

Italy: PHILIPS S.P.A., Sezione Elcoma, Piazza IV Novembre 3, I-20124 MILANO, Tel. 2-6994.

Japan; NIHON PHILIPS CORP., Shuwa Shinagawa Bldg., 26-33 Takanawa 3-chome, Minato-ku, TOKYO (108), Tel. 448-5611.

(IC Products) SIGNETICS JAPAN, LTD., TOKYO, Tel. (03) 230-1521.

Korea: PHILIPS ELECTRONICS (KOREA) LTD., Philips House, 260-199 Itaewon-dong, Yongsan-ku, C.P.O. Box 3680, SEOUL, Tel. 44-4202.

Mexico: ELECTRONICA S.A. de C.V., Varsovia No. 36, MEXICO 6, D.F., Tel. 5-33-11-80.

Netherlands: PHILIPS NEDERLAND B.V., Afd. Elonco, Boschdijk 525, NL-4510 EINDHOVEN, Tel. (040) 79 33 33.

New Zealand: Philips Electrical Ind. Ltd., Elcoma Division, 70-72 Kingsford Smith Street, WELLINGTON, Tel. 873 156.

Norway: ELECTRONICA A/S., Vitaminveien 11, P.O. Box 29, Grefsen, OSLO 4, Tel. (02) 15 05 90.

Peru: CADESA, Jr. IIo, No. 216, Apartado 10132, LIMA, Tel. 27 73 17.

Philippines: ELDAC, Philips Industrial Dev. Inc., 2246 Pasong Tamo, MAKATI-RIZAL, Tel. 86-89-51 to 59.

Portugal PHILIPS PORTUGESA S.A.R.L., Av. Eng. Duharte Pacheco 6, LISBOA 1, Tel. 68 31 21.

Singapore: PHILIPS SINGAPORE PTE LTD., Elcoma Div., POB 340, Toa Payoh CPO, Lorong 1, Toa Payoh, SINGAPORE 12, Tel. 53 88 11.

South Africa: EDAC (Pty.) Ltd., South Park Lane, New Doornfontein, JOHANNESBURG 2001, Tel. 24/6701.

Spain: COPRESA S.A., Balmes 22, BARCELONA 7, Tel. 301 63 12.

Sweden: A.B. ELCOMA, Lidingövägen 50, S-10 250 STOCKHOLM 27, Tel. 08/67 97 80.

Switzerland: PHILIPS A.G., Elcoma Dept., Edenstrasse 20, CH-8027 ZÜRICH, Tel. 01/44 22 11.

Taiwan: PHILIPS TAIWAN LTD., 3rd Fl., San Min Building, 57-1, Chung Shan N. Rd, Section 2, P.O. Box 22978, TAIPEI, Tel. 5513101-5.

Turkey: TÜRK PHILIPS TICARET A.S., EMET Department, Gümüssuyu Cad. 78-80, Beyoglü, ISTANBUL, Tel. 45 32 50.

United Kingdom: MULLARD LTD., Mullard House, Torrington Place, LONDON WC1E 7HD, Tel. 01-580 6633.

United States: (Active devices & Materials) AMPEREX SALES CORP., 230, Duffy Avenue, HICKSVILLE, N.Y. 11802, Tel. (516) 931-6200.

(Passive devices) MEPCO/ELECTRA INC., Columbia Rd., MORRISTOWN, N.J. 07960, Tel. (201) 539-2000.

(IC Products) SIGNETICS CORPORATION, 811 East Argues Avenue, SUNNYVALE, California 94086, Tel. (408) 739-7700.

Uruguay: LUZILECTRON S.A., Rondeau 1567, piso 5, MONTEVIDEO, Tel. 943 21.

Venezuela: IND, VENEZOLANAS PHILIPS S.A., Elcoma Dept., A. Ppal de los Ruices, Edif. Centro Colgate, Apdo 1167, CARACAS, Tel. 36 05 11.

© N.V. Philips' Gloeilampenfabrieken