


MLP65-18/20L



NOTES:

1. 10 sprocket hole pitch cumulative tolerance ± 0.2 .
2. Camber in compliance with EIA 481.
3. Pocket position relative to sprocket hole measured as true position of pocket, not pocket hole.
4. Material: Black conductive or black static dissipative.
5. Tolerances will be ± 0.1 mm unless specified.
6. All measurements in mm unless specified.

| QUANTITY PER REEL | |
|--|-------|
| T1 | 3,000 |
| ECN: S-41948—Rev. B, 25-Oct-04 DWG: 93-5243-x | |