



Audio Precision
5750 SW Arctic Drive
Beaverton, Oregon 97005
Tel: 503-627-0832 Fax: 503-641-8906
U.S. Toll-Free: 1-800-231-7350
e-mail: info@audioprecision.com
web: audioprecision.com

Errata for System Two Cascade *Plus* Specifications: FFT Acquisition Length

Source document specifications control part number NP0020.0001.003,
published in
System Two Cascade Plus Specifications, document part number 8211.0144 rev 1;
and
Getting Started with Cascade Plus, document part number 8211.0142 rev 0.

The specification for **Digital Analyzer: FFT Spectrum Analyzer: Acquisition Length:**
(page 32 in document pn 8211.0144 rev 1; page 40 in document part number 8211.0142
rev 0) was incorrectly listed as

“800 to 256 k samples in 11 steps” (INCORRECT)

This has been changed to

“800 to 4 M samples in 15 steps” (CORRECT)

This change has been made in the revised source document, Specifications Control part number
NP0020.0001.004 and in *System Two Cascade Plus Specifications* document part number 8211.0144 rev 2.