CHAPTER

53

FUSELAGE



CHAPTER 53 FUSELAGE

| Subject/Page | Date | Subject/Page | Date | Subject/Page | Date |
|---------------|-------------|--------------|------|--------------|------|
| EFFECTIVE PAG | BES | | | | |
| 1 | Apr 10/2008 | | | | |
| 2 | BLANK | | | | |
| 53-CONTENTS | | | | | |
| 1 | Apr 10/2006 | | | | |
| 2 | BLANK | | | | |
| 53-30-01 | | | | | |
| 1 | Apr 10/2007 | | | | |
| 2 | Apr 10/2007 | | | | |
| 3 | Apr 10/2007 | | | | |
| 4 | BLANK | | | | |
| 53-50-01 | | | | | |
| 1 | Apr 10/2006 | | | | |
| 2 | Apr 10/2006 | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

A = Added, R = Revised, O = Overflow, D = Deleted

53-EFFECTIVE PAGES

Page 1 Apr 10/2008



TABLE OF CONTENTS

| <u>Subject</u> <u>Title</u> | | Part No. | |
|-----------------------------|-----------------------------------|-----------|--|
| 53- | FUSELAGE | | |
| 53-30-01 | PROBE - FILM RESISTANCE MEASURING | F70328-1 | |
| 53-50-01 | SLING - RADOME | A53001-14 | |

53-CONTENTS

Page 1 Apr 10/2006

PART NUMBER: F70328-1

NAME: PROBE - FILM RESISTANCE MEASURING

AIRPLANE MAINTENANCE: YES

COMPONENT MAINTENANCE: NO

USAGE & DESCRIPTION: The F70328-1 probe is used on all 767 airplanes. F70328 is used to measure


resistance of the electrical bond between conductive coating on

nonconductive plastic sheeting and the grounding fasteners. Conductive coating is appied to almost all external fiberglass and kevlar surfaces except the nose radome. Refer to AMM 51-24-02 and the current F70328 drawing for additional usage instructions. The probe consists of a nylon-cylinder machined to hold the spring-loaded brass probe. The nylon cylinder is capped by a brass collar to hold the probe. Electrical leads from the probe

and retaining collar attach to a customer-supplied multimeter.

DIMENSIONS: 7 x 7 x 11 inches (178 x 178 x 279 mm)






Examples of Panels Requiring Conductive Coating Figure 1

53-30-01





Film Resistance Measuring Probe Figure 2



PART NUMBER: A53001-14

NAME: SLING - RADOME

AIRPLANE MAINTENANCE: YES

COMPONENT MAINTENANCE: NO


USAGE & DESCRIPTION: The A53001-14 sling is used on all 767 airplanes. A53001 is used with

customer-furnished overhead lifting equipment to remove and install the nose radome. Refer to the current A53001 drawing for complete usage instructions. A53001-14 consists of an A53001-3 strap assembly and four

A53001-15 lift bars, all contained in a storage box.

WEIGHT: 10 lbs (4.5 kg)

DIMENSIONS: 305 x 305 x 406 mm)



Radome Sling Figure 1

| REPAIRABLE/REPLACEABLE PARTS | | | | | |
|------------------------------|-----------|-------------------|-------------|--|--|
| ITEM NO. | PART NO. | NOMENCLATURE | VENDOR CODE | | |
| 1 | F70308-2 | PROOF LOAD TAG | | | |
| 2 | A53001-13 | WASHER | | | |
| 3 | A53001-15 | LIFT BAR ASSEMBLY | | | |



| REPAIRABLE/REPLACEABLE PARTS | | | | | | |
|------------------------------|-----------|--------------|-------------|--|--|--|
| ITEM NO. PART NO. | | NOMENCLATURE | VENDOR CODE | | | |
| 4 | CL-10-SHR | HOIST RING | V99862 | | | |