

Service Information

COPIER

☐HARDWARE

☐SOFTWARE

Copyright Canon (UK) Limited

Model: Network Printer Board-F1

Network Multi PDL Printer Board-H1

Ref. No.: 99-OIPD0-B0040

Date: June 4, 1999

Approved by:

Shinya Kishimoto

Location: SYSTEM SOFTWARE

Subject: PATCH FILE 51509.PS RELEASE

Reason: Plain Text File Printing from UNIX

Patch files, 51509.ps(File Size=53016bytes) were released to support the printing plain text files from UNIX for Network Printer Board-F1 v1.01/1.01a and Network Multi PDL Printer Board-H1 v1.0 (the case that Personality is set to PS).

Resolution:

Plain text files sent from UNIX should still print as plain text, but PS files missing the '%!' at the beginning should now print out properly. The threshold to determine if the is PS or plain text is approximately 5 valid PS commands in the file. Above it is treated as PS, below it is treated as plain text.

Installation Notes:

- (1) Download the file 52093.ps to the print or direct queue with Fiery Downloader.
- (2) Reboot the controller.
- (3) Print the configuration page and check that "51509" is printed out in Update Information on the configuration page.