

## Retrofit Status Report / Index

**Model:** GP605P

**Product Group:** 38

**Date** March 2001

| Retrofit Mod. No. | Status | Reason                              | Part Number  | Qty | Serial No. Range     | Issue Date    | Reference Document |
|-------------------|--------|-------------------------------------|--------------|-----|----------------------|---------------|--------------------|
| 01                | C      | Updating IP PCBV32.01/MFC V30.01    | -            |     | DOD00001 to DOD99999 | January 2000  | K1-000043-01       |
| 02                | B      | Electrical Short                    | FY7-0350-000 | 1   | DOD00001 to DOD00158 | June 2000     | K1-000042-UK2      |
| 03                | B      | Safety of Customer Paper Deck Stops | -            | -   | DOD00001 to DOD99999 | November 2000 | ATI-AQ-017         |
| 04                | C      | Updating IP 33.01                   | -            | -   | DOD00001 to DOD99999 | March 2001    | K1-000062-01       |