Advanced Technical Information SY = Systems

ATI No>	Туре	Description / Symptom	Date Issued
SY-049	PS-ZX	Tasks to be performed at installation	
SY-050	GP215 X2e	Driver Status	5/1/99
SY-051	PB-F1	Device auto-configuration function Win '95	19/3/00
SY-052	PS-ZX	Ethernet Boot ROM bug fix	29/4/99
SY-053	PS-7000	Specification and Configuration	18/5/99
SY-054			
SY-055	PB-F1	Version 2 Specification & Configuration	30/9/99
SY-056	PS-ZX30/50 35/55	Upgrading / Downloading of these models	21/10/99
SY-057	CLBP 360PS	Installing Y2K Software Update	18/11/99
SY-058	PS-ZX35/55	Installing / Upgrading System Software Version 2.04	5/5/00
SY-059-1	SAFETY PS-NX40	SAFETY ALERT – Smoke emission from UIB (front panel)	10/07/00
SY-060	Ir5000N/ 6000N	Introduction of iR5000/6000 PostScript	13/02/01
SY-061	G285/335/405, GP605	Mailbox names with CCD PCL v4.51 and above	28/03/01
SY-062	IR5/6000	New System Software, Drivers & Utilities	21/06/01
SY-063	IR2200 Series iR5/6000, iR8500	PostScript Drivers Version 1.11	01/08/00
SY-064	iR-M1 Con.	iR-M1 Controller for iR8500 Series	29/10/01
NOTE:	NW/PB Kits- C1/C2	Differences between C1 & C2 Network Printer Board KitsSEE ATI-AZ-005	
SYS-065	PS-NX5000	Release of patch file 1-4YW4 to overcome ICC output profiles causing controller to hang	11/12/01
SYS-066	PCS BOX	The page control station (PCS Box)	21/12/01
SYS-067	iR-L1 Con.	Systems Information on IR-L1 Controller for iR5000/6000 Series	07/03/02
SYS-068	PB-N1	Systems Information on Printer Board-N1 for iR1600/iR2000 Series	15/02/02
SYS-069	S/Ware	Network ScanGear (All Versions)	29/04/02
SYS-070	iRi 5000i/6000i	iRi cannot send external e-mail	04/07/02
SYS-071	ECopy	Installation Precaution	04/07/02
SYS-072	IR105/8500/7200	Upgrade to FULL and FULL+SEND Functionality	06/08/02

Date: 04/09/02 Author: Pat Bishop

Advanced Technical Information SY = Systems

ATI No>	Туре	Description / Symptom	Date Issued
SY-074	Canon Address Bk Con Utility	Exporting 'Address Book' files from Exchange 5.5 and Exchange 2000, that can be imported into the Canon Address Book Conversion Utility.	04/09/02
END			

Date: 04/09/02 Author: Pat Bishop