

KIO2 MANUAL ERRATA

April 12, 2006 (rev. B-2)

1. **Parts Inventory, page 2:** The Elecraft part number for the AUX2 printed circuit board should be E100126. The quantity shown for the 4-conductor shielded cable should be 10 feet.
2. **Table 1, page 19:** *MixW* Version 2.02 and later includes K2 support (may be listed under Kenwood). *T-R Log* Version 6.63 includes Elecraft K2 as a radio type (with older versions, use TS570 as indicated in the table).
3. **Page 5, seventh step (installing RF chokes L2 – L4):** Slightly larger, less fragile chokes are now supplied for L2 – L4. Please do not try to mount them flush to the board. Instead, they may be mounted one of two ways (whichever way is easiest for you):
 - Mount the chokes at a 45 degree angle, keeping one end as close to the board as possible, *OR*...
 - Mount the chokes horizontally, with both leads bent back under and then bent straight down.