

K2/100 (Appendix G) MANUAL ERRATA

Rev. F-1, October 27, 2009

**THESE MANUAL CORRECTIONS MUST BE MADE
BEFORE YOU BEGIN ASSEMBLY OR YOUR KPA100
MAY NOT FUNCTION CORRECTLY**

1. **Page 6, parts list, C31:** Change the description to: Cap., .22 μ F (“ μ 22J63”) 63V. Change the Part # to E530295.
2. **Page 17, left column, first step:** Change the description of C31 to read: .22 μ F “ μ 22J63”
3. **Page 71, schematic diagram:** Change the value of C31 to .22 μ F. C31 is between Q6 and Q7.