

Tested Bluetooth-Hardware (PC-Interface) and PC-Bluetooth-Protocol-Stacks

ROBO TX Controller Firmware 1.24

Bluetooth-Hardware	Type	Bluetooth-chip set	PC-operating system	PC-Bluetooth-Protocol-Stack	Comment
MSI BToes 2.0 Bluetooth Adapter Class 2	USB-Stick	CSR	Windows XP	Microsoft Bluetooth Protocol Stack	OK
				IVT BlueSoleil V6.4.275.0	OK
Belkin Bluetooth 2.0 Adapter Class 2	USB-Stick	Broadcom ²⁾	Windows XP	WIDCOMM ¹⁾ Bluetooth Software for Windows V5.5.0.7800	not released.
				IVT BlueSoleil V6.4.275.0	OK
DELL Notebook Computer	built-in	Broadcom ²⁾	Windows XP	TOSHIBA Bluetooth Stack for Windows V6.01.03 (D)	OK
PenDrive Bluetooth Adapter V2.0 Class 1 EDR	USB-Stick	CSR	Windows XP	Microsoft Bluetooth Protocol Stack	OK
				IVT BlueSoleil V6.4.275.0	OK
PenDrive Bluetooth Adapter V2.0 Class 2 EDR	USB-Stick	CSR	Windows XP	Microsoft Bluetooth Protocol Stack	OK
				IVT BlueSoleil V6.4.275.0	OK
Bluemax Bluetooth Dongle Class 1	USB-Stick	ISSC	Windows XP	Microsoft Bluetooth Protocol Stack	OK
				IVT BlueSoleil V6.4.275.0	OK
CONRAD BLUETOOTH 3.0+EDR, Best.-Nr: 975462	USB-Micro-Stick	?	Win7, Vista, XP	Microsoft Bluetooth Protocol Stack	OK

MSI BToes 2.1 EDR Micro Dongle	USB- Micro Stick	CSR	Win7, Vista, XP	Microsoft Bluetooth Protocol Stack	Not released. Operating distance very poor
---	------------------------	-----	-----------------	---	--

- 1) The WIDCOMM Software works with Broadcom chip sets only
- 2) The Broadcom Bluetooth-chip sets aren't supported by the Microsoft Bluetooth-Stack