## **Manual Supplement**

Manual Title:51,52,53,54 Series II ServiceSupplement Issue:1Part Number:1276123Issue Date:1/03Print Date:October 1999Page Count:1

Revision/Date:

This supplement contains information necessary to ensure the accuracy of the above manual. Enter the corrections in the manual if either one of the following conditions exist:

- 1. The revision letter stamped on the indicated PCA is equal to or higher than that given with each change.
- 2. No revision letter is indicated at the beginning of the change.



## Change #1

On page 8, under *Verification of IR Communications Port (Fluke 53 and 54)*, add step 3A as follows:

3A. On the Fluke 53 or 54, press then **RECALL**.

1/03