## **Manual Supplement**

Manual Title: 5700A/5720A Getting Started Part Number: 1668111 Print Date: March 2002 Revision/Date:

Supplement Issue: 1 Issue Date: Page Count: 1

3/04

This supplement contains information necessary to ensure the accuracy of the above manual. Enter the corrections in the manual if either one of the following conditions exist:

- The revision letter stamped on the indicated PCA is equal to or higher 1. than that given with each change.
- 2. No revision letter is indicated at the beginning of the change.



## Change #1

On pages 27 and 28, Tables 17 and Table 18, replace the footnote with the following:

Note: Maximum output from the calibrator's terminals is 2.2 A. Uncertainty specifications for 220  $\mu$ A and 2.2 mA ranges are increased by a factor of 1.3 plus 2  $\mu$ A when supplied through 5725A terminals. For the 5720A 220  $\mu$ A range, 1 kHz-5 kHz and 5 kHz-10 kHz, when the output is coming from the Aux Current terminals, use the 5700A Absolute Uncertainty specifications. Specifications are otherwise identical for all other output locations.