

# Manual Supplement

Manual Title: 5725A  
Part Number: 823435  
Print Date: January 1989  
Revision/Date: 6, 6/96

Supplement Issue: 1  
Issue Date: 6/96  
Page Count: 1

---

---

This supplement contains information necessary to ensure the accuracy of the above manual. Enter the corrections in the manual if either one of the following conditions exist:

1. The revision letter stamped on the indicated PCA is equal to or higher than that given with each change.
2. No revision letter is indicated at the beginning of the change.

## Change #1

On page 6-8, replace the first sentence in the Warning with the last sentence in step 6.

On page 6-9, paragraph 6-8, replace step 2 with:

2. Return the High Voltage Amplifier assembly (A3) (and the Current Amplifier assembly (A2) if it has been accessed) to the normal position, and reinstall the assembly retaining screws.

Replace the last *Note* with:

*Note*

*When reinstalling the assembly, lower it into place squarely to make sure its connector seats correctly in the Interconnect assembly connector. Ensure that both J301 and J303 are properly aligned and connected to their respective cables.*

On page 6-11, paragraph 6-10, following the WARNING statement:

Change: The Current Amplifier assembly lays flat on the top of the instrument, toward the front...

To: The Current Amplifier assembly lays flat on the top of the instrument, toward the **rear**...

On page 6-12, paragraph 6-11, change the first sentence:

From: The High Voltage Amplifier assembly lays flat on the top of the instrument, toward the rear.

To: The High Voltage Amplifier assembly lays flat on the top of the instrument, toward the **front**.

On page 6-13, paragraph 6-12, make the following changes:

Change: The High Voltage Sense assembly lays flat on the top of the instrument

To: The High Voltage Sense assembly lays flat on the **bottom** of the instrument

Change step 2 to step 2a and add a new step 2 as follows:

2. Follow the Current Amplifier Assembly (A2) access procedure to gain access to the connectors on the High Voltage Sense Assembly (A6). Remove the connectors and secure the Current Amplifier Assembly before proceeding.