

Manual Supplement

Manual Title:	9040/9040K Users	Supplement Issue:	1
Part Number:	2438546	Issue Date:	2/06
Print Date:	April 2005	Page Count:	2
Revision/Date:			

This supplement contains information necessary to ensure the accuracy of the above manual.

Change #1

On page 2, under ***Unpacking the 9040***, add the following:

- Fused Test Probe

On page 8, under the last **Caution**, add the following:

Replacing the Fuse

Warning

Prior to fuse replacement, disconnect the accessory (cable or probe) or both ends.

Only use fuses of the correct voltage and current as shown in the Specifications section. Using incorrect fuses can cause probe damage or serious bodily injury.

1. Check the fuse using a simple continuity test.
2. Hold the probe in front of the finger guard and unscrew the tip in a counter-clockwise direction.
3. Remove the defective fuse from the fuse holder.
4. Insert a new fuse in the fuse holder and reassemble the probe.

On page 9, add the following prior to ***Safety Specifications:***

Fuse	500 mA / 1000 V / FF/ 50 kA / (6.3 x 32 mm)
-------------	--