CHARACTERISTICS

SPECIFICATIONS

ADDITIONAL INFORMATION

2.23 ACCESSORIES

* Accessories furnished with

instrument:

Users Manual

Quick Operating Guide

PM 8918/002

 $2 \times 10 \text{ M}\Omega$ 10:1 Passive Probe,

1.5m.

ScopeMeter Accessory set:

2 x HF adapter

2 x High voltage testpin

2 x Earth lead

2 x Trim screwdriver

4 mm adapter

Banana to BNC adapter

PM9081/001

shrouded.

1.5m.

Set Testleads and Testpins:

2 x testleads

2 x testpins

2 x banana adapter

Holster

C 75

PM 9083/001

Power Adaptor/Battery

Accessory case

Charger:

PM 8907/001

PM 8907/003 PM 8907/004 PM 8907/008 Depends on model:

Universal Europe. North American. United Kingdom. Universal 115V/ 230V.

PM9080/001 (Model 97 only)

RS-232-C Interface

2.24 SERVICE AND MAINTENANCE

* Main Time Between

Failures (MTBF)

40 000 hours

Predicted value, calculated through parts counting method, according

to MIL HDBK- 217E.

* Calibration Interval

1 year

Mean Time To Calibrate

ate

(MTTC)

30 minutes