

FLUKE®

FlukeView® Forms

Documenting Software
Including FlukeView® Form Designer

Installation Guide

PN 1286143 September 1999

© 1999 Fluke Corporation. All rights reserved. Printed in USA

All product names are trademarks of their respective companies.

FlukeView Forms Installation Guide

FlukeView Forms Documenting Software acquires and documents readings from compatible Fluke meters. This guide describes how to install and start *FlukeView Forms* and *FlukeView Forms Designer*.

System Requirements

Operating System: Microsoft Windows 95, Windows 98, or Windows NT 4.0.

Recommended hardware: Pentium microprocessor, 32 MB RAM, and 40 MB hard disk space (60 MB to install).

Note

To install the software on Windows NT, you must log on as a Windows NT Administrator.

Installing FlukeView Forms from the CD

If your PC does not contain a CD-ROM drive, skip to the section, "Installing *FlukeView Forms* from Floppy Disks."

1. Insert the CD into your CD-ROM drive.
2. Click **Start** on the Windows taskbar.
3. Choose **Run** from the **Start** menu.
4. Type *d:\install.exe* (where *d* is your CD-ROM drive letter)
5. Click **OK**.
6. Follow the installation instructions that appear.

Starting FlukeView Forms

The Installation program installs Start menu items for *FlukeView Forms* and *FlukeView Form Designer*. To start a program, select the program from the Start menu.

Installing FlukeView Forms from Floppy Disks

Copying the Setup Program to Floppy Disks

Have blank, formatted 1.44 MB floppy disks available.

1. Insert the CD into a PC that contains a CD-ROM drive.
2. Type *d:\English* (where *d* is the CD-ROM drive letter).
The folder contains folders named *Disk1*, *Disk2*, ...
3. For each folder named *Disk1*, *Disk2*, ... on the CD, label a blank, formatted 1.44 MB floppy disk with the folder name.
4. Copy the files in folders *Disk1*, *Disk2*, ... on the CD to the floppy disks labeled *Disk1*, *Disk2*, ..., respectively.
5. If you are installing *FlukeView Forms* on Windows 95, create a blank formatted disk, label it *DCOM95*, and copy the file *D:\IDCOM95\dcom95.exe* from the CD to the *DCOM95* floppy disk.
6. Read the next section "Installing FlukeView Forms from Floppy Disks."

Installing from Floppy Disks

1. If you are installing *FlukeView Forms* on Windows 95:
 - Insert the *DCOM95* floppy disk into the floppy disk drive.
 - Click **Start** on the Windows taskbar.
 - Choose **Run** from the **Start** menu.
 - Type *a:\DCOM95.exe* (where *a*: is your floppy disk drive letter).
After the program finishes, it restarts your PC.
2. Insert *Disk1* into the floppy disk drive.
3. Click **Start** on the Windows taskbar.
4. Choose **Run** from the **Start** menu.
5. Type *a:\setup.exe* (where *a* is your floppy drive letter.)
6. Click **OK**.
7. Follow the installation instructions that appear.
The setup program prompts you to switch disks.
8. For instructions on how to run the *FlukeView Forms* and *FlukeView Form Designer*, read the section "Starting FlukeView Forms" (page 2).