



PACKING LIST FOR FAR2117BB/DC

For Internal Use Only

Serial No. 4318 -
 Checked By:
 Tech _____
 Date _____

RPU013/DC

Yes	Remarks
	sub 008-535-940
	"
	"
	008-535-910
	008-535-950

Box 1 - Processor Unit Wt: 29 lbs. Dim: 19" x 21" x 12"

Part No.	Description	Quantity
1 RPU013/DC	Processor Unit 24vDC	1
2 000-808-981	Terminal Spanner Tool "20mm"	1
3 000-147-517	Terminal Spanner Tool "19mm"	1
4 000-538-118	Crimp Lug FV2-4	2
5 000-549-065	Fuse FGBO 10 for "AC" Unit	4
6 000-549-015	Fuse FGBO 20 for "DC" Unit	4
7 IME-351-90Z	Installation Manual	1
8 OME-351-90Z	Operator's Manual	1

RCU-014

Yes	Remarks
	sub 008-535-610
	"
	"
	"
	sub CP03-25604

Box 2 - Control Unit Wt: 10 lbs. Dim: 11" x 19" x 8"

Part No.	Description	Quantity
1 RCU014	Control Unit w/ Cable Assembly	1
2 100-306-251	Fixing Bracket	1
3 000-147-167	Grommet "G39"	1
4 000-803-043	"3M" Brand Bumper Cushion	3
5 000-881-447	Washer Head Screw M4 x 12	2
6 000-881-447	Washer Head Screw M4 x 12	4

RSB096-078

Yes	Remarks
	sub 008-535-550
	"
	"
	"
	"
	"
	"
	"
	"
	"
	"
	"
	sub 008-435-860

Box 3 - Gearbox Wt: 71 lbs. Dim: 16" x 23" x 24"

Part No.	Description	Quantity
1 RSB096-078	Gearbox w/ RTR078 12KW Xceiver	1
2 300-130-010	Corrosion Proof Mat	1
3 300-130-020	Seal Washer	4
4 000-808-981	Terminal Spanner Tool	1
5 000-538-123	Crimp Lug FV5.5-4	1
6 000-863-112	Hex Nut M12	4
7 000-864-132	Flat Washer M12	4
8 000-864-263	Spring Washer M12	4
9 000-862-191	Hex Bolt M12x60	4
10 000-863-109	Nex Nut M6	1
11 000-863-129	Flat Washer M6	3
12 000-864-260	Spring Washer M6	1
13 000-862-180	Hex Bolt M6x25	1
14 000-566-000	Grounding Wire	1
15 000-631-716	Motor Brush	2

000-149-193

Yes	Remarks

Box 4 - Cable Wt: 58 lbs. Dim: 19" x 21" x 12"

Part No.	Description	Quantity
1 000-149-193	30M Cable Assembly	1

Rev 12-17-07