



E4981A Capacitance Meter, 120 Hz/ 1 kHz/ 1 MHz Firmware Revision History

Rev. 20150409

Note:

The purpose of this document is to provide an overview of important changes that could affect a majority of customers. If you have any concerns about a specific issue, contact your local Keysight representative.

Revision A.03.11 ... Released Apr. 2015

1. Support new LCD/FPGA

Revision A.03.10 ... Released Apr. 2015

1. Support old LCD/FPGA

Revision 1.10 ... Released Oct. 2009

1. Fixed bug on I/O error through device using USB control

Note: For MY48100471 and above, the firmware revision 1.10 and later can be only installed.
Do NOT attempt to install the older firmware revisions.

Revision 1.01 ... Released Dec. 2008

1. Revised digital I/F program revision check.

Revision 1.00 ... Released Oct. 2008

1. Initial Release