

### Pyrex and Teflon Cleaning

1. Degrease the parts/wares in acetone
2. Prepare fresh mixture of Piranha solution  
( $\text{H}_2\text{SO}_4:\text{H}_2\text{O}_2=1:1$ ) in a Teflon beaker or container
3. Put Teflon and pyrex parts in it and leave for 10 min
4. Rinse thoroughly in DI water and blow dry with  $\text{N}_2$ .