Agilent 4263B LCR Meter

Manual Change

Agilent Part No. 04263-90004

May 2003

Printed in Japan

Miscellaneous Changes

1. The option system of the 4263B has changed since May 2003. Apply the following changes.

| Old Option Number | New Option Number | remarks |
|---|-------------------------------------|---------|
| 001 (Add N/M/DC-R measurement function) | same as the left number | |
| 002 (Add 20 kHz test frequency) | same as the left number | |
| 1CM (Rack Mount Kit) | same as the left number | |
| 1CN (Handle Kit) | same as the left number | |
| AB0 (Taiwan – Chinese localization) | _ | 1,2 |
| _ | AB0 (Taiwan – Chinese localization) |] |
| AB1 (Korea – Korean localization) | _ |] |
| _ | AB1 (Korea – Korean localization) | 1 |
| AB2 (China – Chinese localization) | _ | 1 |
| _ | AB2 (China – Chinese localization) | 1 |
| ABA (U.S. – English localization) | _ | 2 |
| _ | ABA (U.S. – English localization) | 1 |
| ABD (Germany – German localization) | _ | 1,2 |
| _ | ABD (Germany – German localization) | |
| ABE (Spain – Spanish localization) | _ | 1 |
| _ | ABE (Spain – Spanish localization) | |
| ABF (France – French localization) | _ | 1 |
| _ | ABF (France – French localization) | 1 |
| ABJ (Japan – Japanese localization) | _ | 2 |
| _ | ABJ (Japan – Japanese localization) | |
| ABZ (Italy – Italian localization) | | 1,2 |
| - | ABZ (Italy – Italian localization) | |
| 0BW (Add Service Manual) | same as the left number | |
| 0B0 (Delete Operation Manual) | _ | 3 |
| 0B1 (Add Operation Manual) | _ |] |

1. The Chinese/Korean/German/Spanish/French/Italian operation manual has been edited by translating part of the whole English operation manual. For detailed information on the 4263B, also refer to the English operation manual of the 4263B.

- 2. In the previous system, the option number is used to choose the language of the operation manual (standard accessory). In the new option system, it is used to add an operation manual (optional accessory) of the language the customer desires.
- 3. No selection of addition/deletion is required for the operation manual because it is only available as an optional accessory in the new option system.
- **2.** CD-ROM that contains the contents of the 4263B Operation Manual is furnished as a standard content.