

## Agilent 42841A Bias Current Source

# Manual Change

Agilent Part No. 42841-90001

February 2003

Printed in Japan

### Change 1

Change option numbers described in Operation Manual.

Old Option Number	New Option Number	Remark
907 (Front Handle Kit)	same as the left number	
908 (Rack Mount Kit)	same as the left number	
909 (Rack Flange and Handle Kit)	same as the left number	
-	ABA (Add Operation Manual (English))	1
-	ABJ (Add Operation Manual (Japanese))	
915 (Add Service Manual)	same as the left number	

1. In the previous system, the option number is used to choose the language of the operation manual (standard accessory). In the new option system, it is used to add an operation manual (optional accessory) of the language the customer desires.