

S E R V I C E N O T E

SUPERSEDES: NONE

4339A High Resistance Meter

Serial Numbers: 0000J00000 / 3148J00266

Duplicate Service Notes: None

Troubleshooting tip of Intermittent E11 ADC FAILURE

Parts Required:

P/N	Description	Qty.
04339-85101	ROM, Rev. 01.01	1

Solution/Action:

If a 4339A exhibits intermittent ADC FAILURE (E11), replacing the ROM from revision 01.00 to 01.01 may solve the phenomena.

DATE: 24 JUNE 1992

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
YO	3355	