

S E R V I C E N O T E

SUPERSEDES: None

**3560A Portable Dual Channel Dynamic Signal Analyzer**

**Serial Numbers:** 0000A00000 / 9999Z99999

**3560A Replacement Power Pack for US and Canada Only**

**Situation:**

The power supply pack listed in the manuals for use in the United States and Canada is 82241-60001. This part is obsolete and no longer available.

**Solution/Action:**

A new part had been setup to replace this power supply pack for use in the USA and Canada. The new part number for this replacement power supply pack is 5183-2823.

DATE: **January 1999**

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
<b>INFORMATION ONLY</b>		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
MJL	A100	USA and Canada Only