

S E R V I C E N O T E

SUPERSEDES: 5342A-35B

5342A Microwave Frequency Counter

Serial Numbers: 0000A00000 / 2317A07386

Front Panel Replacement Kit

To Be Performed By: Agilent-Qualified Personnel or Customers

Parts Required:

05342-60205 5342A Front Panel Replacement Kit

Situation:

5342As made before 1983 used laminated plastic front panels which tend to discolor and delaminate with age, particularly when subjected to elevated temperature for extended periods of time. Because the new improved panels are quite different in design, replacement requires several new parts.

Solution/Action:

The new parts are available in a kit, which will work whether the unit had the standby LED or not. Kit 05342-60205 contains an installation note, which lists all parts for eventual individual replacement if ever necessary. The installation note can be purchased separately as part number 05342-90050.

DATE: May 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 1.5 Hour
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: CJF	ENTITY: 0200	AGILENT RESPONSIBLE UNTIL: 31 January 1988	
		ADDITIONAL INFORMATION:	