

**6572A-04**

# S E R V I C E N O T E

Supersedes:  
NONE

## 6572A 2KW General Purpose Power Supply

Serial Numbers: 3626A-00218 / 9999Z99999

### Front Panel Parts List

#### Situation:

When damage occurs to the front panel portion of the power supply, several replacement parts may be required to repair the instrument.

#### Solution:

This is a parts list for convenience that lists the commonly replaced front panel parts.

Non-System units with earlier serial numbers, that need new optical encoders must order a new initialized "Tested Keypad PCA" p/n **06572-61001**. (System / GP-IB units use p/n **5060-3400** and need to be initialized to the correct model number.)

**NOTE:** When replacing the keypad PCA the unit will need to be aligned / calibrated.

**5064-0126** ASSY-FR PNL, SERIVCE KIT is Obsolete, and is no longer available.

#### Available Front Panel Parts:

<u>Part Number</u>	<u>Quantity</u>	<u>Description</u>
0370-3238	2	KNOB 6mm
0515-0374	2	SCR-MACHINE
0515-2535	1	SCREW-METRIC
0960-0912	2	ENCODER-ROTARY
1000-0842	1	WINDOW

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR: RJM      PRODUCT LINE: 33

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002  
PRINTED IN U.S.A.



June 27, 2002

5001-0539	2	TRIM SIDES, FRONT GRAY
5001-6748	1	FRONT PANEL (Overlay)
5040-1735	1	KEYPAD
06572-80001	1	NAMEPLATE
5040-1703	1	FRONT FRAME