



16517A/18A Probe Repair Instruction Sheet

To replace a probe tip

To replace a faulty or broken probe tip, refer to “To replace a probe lead,” found in chapter 6 of the *16517A/18A 4-GSa/s Timing and 1-GSa/s Synchronous State Logic Analyzer Service Guide*.

To order more Probe Tip Kits, order part number 5081-7753 (Qty 3).



