

16702A-04

Serial Numbers:

US00000000 / US39159999

Y2K update information. Product requires Software update revision 1.40

To Be Performed By: HP-Qualified Personnel, and customer

Parts Required:

HP P/N	Description	Quantity
B3760-68712	SW Update CD-ROM v1.40	1

December 1996 Serial Number:

US00000000

Situation:

The HP 16702A Logic Analysis System mainframe operating system runs on top of HP-UX 10.20. At product release, the HP-UX 10.20 infrastructure operating system included with the mainframe did not include Y2K patches.

Solution / Action:

Install operating system software revision 1.40 using the procedure provided with the update CD-ROM.

Operating system software version 1.40 includes the Y2K patches for the infrastructure HP-UX 10.20 operating system. Note that the HP 16702A mainframe currently passes HP's date roll tests. However the B4600-series Tool Sets running in the mainframe may display the year 2000 as "100".

Date:

21 May 1999

```
*****
*
*           MODIFICATION RECOMMENDED           *
*           -----                           *
*
*           STANDARDS: LABOR HOURS _0.5_____ *
* ACTION CATEGORY: ON SPECIFIED FAILURE ___ IMMEDIATELY ___ *
*                   AGREEABLE TIME XX         *
* LOCATION CATEGORY: CUSTOMER INSTALLABLE XX   ON-SITE XX *
*                   HP LOCATION XX           *
* AVAILABILITY: PRODUCT'S SUPPORT LIFE        *
* SERVICE INVENTORY: RETURN ___ SCRAP ___     SEE TEXT ___ *
*                   USED PARTS: RETURN ___ SCRAP ___ SEE TEXT ___ *
* HP RESPONSIBLE UNTIL: _02 Nov 2000_         *
* AUTHOR/ENTITY: _RB/0800_____              *
* ADDITIONAL INFO: _____                *
*****
```