

# Installation Note

---

**Agilent Technologies**  
**Kit Number 08711-60058 and**  
**Kit Number 08712-60036**



**Part Number 08711-90103**  
**Printed in USA May 2001**  
Supersedes July 1996

**Notice.**

The information contained in this document is subject to change without notice.

Agilent Technologies makes no warranty of any kind with regard to this material, including but not limited to, the implied warranties of merchantability and fitness for a particular purpose. Agilent Technologies shall not be liable for errors contained herein or for incidental or consequential damages in connection with the furnishing, performance, or use of this material.

PRODUCTS AFFECTED: Agilent 8711B/12B/13B/14B and  
Agilent 8711C/12C/13C/14C  
RF Network Analyzers and  
Agilent 8730A Tuner Analyzer

SERIAL NUMBERS: All

TO BE PERFORMED BY:  Agilent Service Center  
 Customer or Personnel Qualified by  
Agilent  
 Agilent Personnel On-site

ESTIMATED INSTALLATION TIME: 5 minutes

---

## Description

This kit provides the hardware necessary to install rack mount flanges with handles on your analyzer. See caution below before installing.

---

## Tools Required

#15 Torx driver

---

**Caution** The rack mount kit you ordered comes with a standard rack mount kit and eight extra M4 X 20 screws (part number 0515-0686). Use these screws instead of the screws enclosed within the standard rack mount kit. The shorter screws in the standard rack mount kit will not properly secure the rack mount flanges.

---

---

## For Additional Information

By internet, phone, or fax, get assistance with all your test & measurement needs.

**Table 1-1. Agilent Technologies Sales and Service Offices**

**Online Assistance:** [www.agilent.com/find/assist](http://www.agilent.com/find/assist)

<b>United States</b> (tel) 1 800 452 4844	<b>Japan</b> (tel) (81) 426 56 7832 (fax) (81) 426 56 7840	<b>New Zealand</b> (tel) 0 800 738 378 (fax) 64 4 495 8950
<b>Canada</b> (tel) 1 877 894 4414 (fax) (905) 206 4120	<b>Latin America</b> (tel) (305) 269 7500 (fax) (305) 269 7599	<b>Asia Pacific</b> (tel) (852) 3197 7777 (fax) (852) 2506 9284
<b>Europe</b> (tel) (31 20) 547 2323 (fax) (31 20) 547 2390	<b>Australia</b> (tel) 1 800 629 485 (fax) (61 3) 9210 5947	