

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

8753ET-04

S E R V I C E N O T E

Supersedes:
None

8753ET Vector Network Analyzer

Serial Numbers: [0000A00000 / 9999Z99999]

**Uncorrected Port Performance and Calibration Coefficients Specification
change**

Parts Required:

P/N	Description	Qty.
08753-900484	8753ET/ES Service Guide	

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: [initials]	PRODUCT LINE: WN
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2002
PRINTED IN U.S.A.



November 7, 2002

Situation:

All editions of the 8753ES/ET Service Guides part number 08753-90484 page 2-50 has the incorrect Uncorrected Error Terms specification for Reflection Tracking and Transmission Tracking.

Solution/Action:

Specification change:

Transmission Tracking/ Reflection Tracking

Frequency Range 300kHz to 1.3GHz specification change ± 1.5 dB.

Frequency Range 1.3GHz to 3GHz specification change ± 1.5 dB.

Frequency Range 3GHz to 6GHz specification change ± 2.5 dB.

Make the above change to the 8753ES/ET Service Guide 08753-90484 pages 2-50.