MODIFICATION AVAILABLE - SERVICE/RELIABILITY EHMANCEMENT CHARGEABLE TO CUSTOMER WARRANTY.

E8361A-03

<u>SERVICE NOTE</u>

Supersedes: NONE

E8361A Option 014 PNA Microwave Network Analyzers

Serial Numbers: ALL

A guard is available to protect the front-panel jumper cables during shipment.

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

P/N: Description: Qty.

E8361-00009 Guard, jumper cables 2

ADMINISTRATIVE INFORMATION

| SERVICE NOTE CLASSIFICATION: | | |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------|-------------------------------------------------------------|
| MODIFICATION AVAILABLE | | |
| ACTION CATEGORY: | AGREEABLE TIME | PERFORMANCE ENHANCEMENT X SERVICE / RELIABILITY ENHANCEMENT |
| LOCATION CATEGORY: | CUSTOMER INSTALLABLE ON-SITE X SERVICE CENTER | AVAILABLE UNTIL: Product's support life. |
| AUTHOR: MF PRODUCT LINE: WN ADDITIONAL INFORMATION: This Service Note applies to the following PNA models: E8361/3/4A Option 014, E8363/4B Option 014, and N5230A Options 425 & 525. | | |

© AGILENT TECHNOLOGIES, INC. 2005 PRINTED IN U.S.A.



Page 2 of 2 E8361A-03

Situation:

A guard is available to protect the front-panel jumper cables from being damaged during shipment.

Solution/Action:

Two guards should be installed to cover the front-panel jumper cables before the PNA is returned to the customer. The guards are identical, so either one can be used to cover the left or right-side jumper cables. The guards simply require a push-on installation, so no tools are necessary. To install, push each guard over the jumper cables until its cushioning material touches the front panel of the PNA.