

## S E R V I C E N O T E

SUPERSEDES: NONE

**8991A Peak Power Analyzer**

Serial Numbers: 0000A00000 / 9999Z99999

**Save A1 control board assembly top and bottom shields****Duplicate Service Notes:**

8990A-01

8991A-01

8992A-01

**Situation:**

The two top and bottom shields for the channels 1 and 4 inputs are not structured to the A1 control board. They will not be on the replacement board.

**Solution/Action:**

After removing the A1 Control board assembly: Remove both the top and bottom shields from channels 1 and 4. Save all hardware. Install these shields onto the replacement board prior to installing the board into the unit.

DATE: 23 November 1993

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR:

EM

ENTITY:

5300

ADDITIONAL INFORMATION: