S E R V I C E N O T E

SUPERSEDES: NONE

8991A Peak Power Analyzer

Serial Numbers: 0000A00000 / 3314A00211

Part number correction for the A1 control board assembly

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

Part No. Description

08991-60161 8991A A1 Part Number Modification Kit

Situation:

instruments within the above serial range were shipped missing the part number label on the A1 Control Board Assy. These boards should be labeled "08991-60005".

Solution/Action:

When servicing the A1 Control board assembly: Order kit 08991-60161 to change A1 assy part number from 08990-60001 to 08991-60005. When ordering this Assy, use part number 08991-60005 (replacement Assy) or part number 08991-69005 (restored Assy).

DATE: 30 November 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY	
5300	
	INFORMAT ENTITY:

© 1993 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

