

11757A-05

HP 11757A/B Multipath Fading Simulator

HP 11758A/B Digital Radio Test Set

HP 11758T/U/V Digital Radio Test System

Serial Numbers:

0000A00000 / 3306U00000

Y2K update information:

Products Non-Y2K compliant, and Non-Upgradable

December 1996 Serial Numbers:

11757B - 3611U00170

11758B - 3611U00300

Situation:

Products with the serial numbers, as given above, have been designated non-Y2K compliant, without the ability to be upgraded. The reasons are as follows:

(i) 11757B's and 11758B's have a Y2K non-compliance issue as described in service note 11757B-05. Due to hardware incompatibility, upgrading to achieve compliance (also described in these service notes) is not possible.

(ii) It is likely that 11757A's and 11758A's will not have the same Y2K non-compliance issues as that described in 11757B-05. However, as it has not been possible to physically verify the compliance of these products, a non-compliant status has been designated. In instances such as these, customers may submit a product for a full Y2K compliance assessment, if desired.

For similar reasons to those described in (i) above, the 11757A and 11758A are not, in any case, upgradable.

(iii) This service note also applies to any HP 11758A or HP 11758B, having an applicable serial number, which is a part of a DiRTS system, such as the HP 11758T/U/V.

Date:

2nd October 1998

```

*****
*
*                               INFORMATION ONLY
*                               -----
*
*   AUTHOR/ENTITY: BC/E600_____
*   ADDITIONAL INFO: _____
*
*****

```