

S E R V I C E N O T E

SUPERSEDES: None

11758V Digital Radio Test System

Serial Numbers:0000A00000 / 9999Z99999

11758-90034 User Guide, Section 2, Installation and Verification**Situation:**

There is an error in this User Guide regarding the 3-tone source check. Using the equipment shown in the Guide, (11758-90034), in Figure 2-6 on page 2-24. Section 6 of the procedure reads, "Look for a level of approximately -11 dBm per tone".

Solution / Action:

Using the equipment shown in the Guide, (11758-90034), in Figure 2-6 on page 2-24. Section 6 of the procedure should read, "Look for a level of approximately -18.5 dBm per tone".

For the 6-Tone Source Option, the level for the upper frequency tones should be approximately -21.5 dBm per tone.

DATE: July 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

BC

ENTITY:

E600

ADDITIONAL INFORMATION: