85620A-05

SERVICE NOT	Ε
-------------	---

SUPERSEDES: NONE

## 85620A Mass Memory Module

Serial Numbers: 0000A00000 / 9999A99999

Duplicate Service Notes: None

# Downloadable programs written on later modules may not be fully compatible with earlier modules.

#### Situation:

A significant redesign was done to the 85620A Mass Memory Module which added more capability, commands and functions. Modules with serial numbers 3143A01968 and later reflect these changes. In addition, the later modules are easily recognized by the presence of a 9-pin auxiliary connector. Downloadable programs (DLPs) which are written on the later modules will likely not work with the earlier units which have serials 3003A01967 and earlier. They may even cause the module to "hang up" until power is cycled.

#### Solution/Action:

Do not attempt to run DLPs written on Mass Memory Modules with serial prefixes 3143A or later on earlier modules.

DATE: 22 November 1993

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
INFORMATION ONLY			
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:	
GPB	5300		

© 1993 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

