8563A-13

SUPERSEDES: 8563A Portable Spectrum Analyzer Serial Numbers: 0000A00000 / 3133A00908 Duplicate Service Notes: 8560A-17 8561A-30 8561B-19 8562A-61 8562B-59 8563A-13 Modifying instruments for use with 85644A and 85645A Por Capability To Be Performed By: Agilent-Qualified Personnel or Customer	: None
Serial Numbers: 0000A00000 / 3133A00908 Duplicate Service Notes: 8560A-17 8561A-30 8561B-19 8562A-61 8562B-59 8563A-13 Modifying instruments for use with 85644A and 85645A Po Capability	
Duplicate Service Notes: 8560A-17 8561A-30 8561B-19 8562A-61 8562B-59 8563A-13 Modifying instruments for use with 85644A and 85645A Po Capability	
8560A-17 8561A-30 8561B-19 8562A-61 8562B-59 8563A-13 Modifying instruments for use with 85644A and 85645A Po Capability	
8561A-30 8561B-19 8562A-61 8562B-59 8563A-13 Modifying instruments for use with 85644A and 85645A Po Capability	
8561B-19 8562A-61 8562B-59 8563A-13 Modifying instruments for use with 85644A and 85645A Po Capability	
8562A-61 8562B-59 8563A-13 Modifying instruments for use with 85644A and 85645A Po Capability	
8562B-59 8563A-13 Modifying instruments for use with 85644A and 85645A Po Capability	
8563A-13 Modifying instruments for use with 85644A and 85645A Po Capability	
Modifying instruments for use with 85644A and 85645A Po Capability	
Capability	
Parts Required:	
85645-60009 Power Sweep Retrofit Kit	
Situation:	
The 85645 and 85644 Tracking Sources will operate with standard 856X R	
Spectrum Analyzers with the exception of the Power Sweep function. Instru	
serial number ranges noted above, as well as those with higher serial numb option 005, need to be modified to use the Power Sweep capability.	pers without
DATE: 27 Noven	Continue

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: MODIFICATION AVAILABLE			
ACTION CATEGORY:	AGREEABLE TIME	■ PERFORMANCE ENHANCEMENT □ SERVICE/RELIABILITY ENHANCEMENT	
LOCATION CATEGORY:	CUSTOMER INSTALLABLE	AVAILABLE UNTIL: Product Support Life	
AUTHOR: GPB	ENTITY: 5300	ADDITIONAL INFORMATION:	

© 1991 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Solution/Action:

Install the Power Sweep Retrofit kit in order to use the Power Sweep capability. The kit adds a BNC connector to the rear panel of the spectrum analyzer to provide a Power Sweep ramp for the tracking source.