

## S E R V I C E N O T E

SUPERSEDES: None

**85645A Microwave Tracking Source**

Serial Numbers: 0000A00000 / 9999A99999

**Duplicate Service Notes:**

85644A-01

85645A-01

**Firmware Upgrade Kit****To Be Performed By:** Agilent-Qualified Personnel or Customer**Parts Required:**

ROM Upgrade Kit, part number 85645-60020

**Situation:**

Later versions of instrument firmware sometimes are implemented to improve instrument performance and reliability.

**Solution/Action:**

A firmware upgrade kit has been set up for 85644A and 85645A Microwave Tracking Sources. The kit contains the latest revision instrument firmware and the applicable installation note. Table 1 lists the contents of the kit.

*Continued*

DATE: 24 August 1992

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
<b>MODIFICATION AVAILABLE</b>		
ACTION CATEGORY:	<b>AGREEABLE TIME</b>	<input checked="" type="checkbox"/> PERFORMANCE ENHANCEMENT <input type="checkbox"/> SERVICE/RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	AVAILABLE UNTIL: Support Life
AUTHOR: GPB	ENTITY: 5300	ADDITIONAL INFORMATION:

**Table 1: ROM Upgrade Kit, Part Number 85645-60020**

<b>Part No.</b>	<b>Description</b>	<b>Qty.</b>
85645-80004	UVEPROM, Programmed A3U18	1
85645-80005	UVEPROM, Programmed A3U78	1
85645-90024	Installation Note	1