								85	65E-	-18		
S	Е	R	V	Т	С	Е	Ν	0	Т	Е		
	SUPERSEDES: None 8565 E Series Portable Spectrum Analyzers											
	Serial Numbers: See below											
	A1A2 RPG Assembly and A1 Keyboard Part Number Change											
	Duplicate Service Notes:											
	8560E-23Serial Numbers: 0000A00000/3728A031978561E-19Serial Numbers: 0000A00000/3728A020408562E-11Serial Numbers: 0000A00000/3728A005178563A-25Serial Numbers: 0000A00000/3729A042688563E-23Serial Numbers: 0000A00000/3728A077048564E-18Serial Numbers: 0000A00000/3728A009288565E-18Serial Numbers: 0000A00000/3728A00768To Be Performed By: Agilent-Qualified Personnel, CustomerParts Required: See Text											
	Situation:											
	The original A1A2 Rotary Pulse Generator (RPG), 0960-0745, has been discontinued by the manufacturer. A new RPG, 1990-1525 is used in all instruments with serials above those listed. To accomodate the new RPG, the A1 Keyboard Assembly and the RPG knob were also changed. The old parts are kept on Replacement for older units, so retrofits are not necessary.											
									Contir	wed		
	DATE: January 1999											

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICA	ATION:								
INFORMATION ONLY									
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:							
GPB	5320								
© 1999 AGILENT TEC PRINTED IN U.S.A.	HNOLOGIES	Agilent Technologies							

Solution / Action:

Order replacement part numbers for the RPG, keyboard and knob according to the table below.

Description	P/N for Old Serials	P/N for New Serials
A1A2 RPG	0960-0745	1990-1525
A1 Keyboard Ay	08562-60140	08562-60190
RPG Knob	0370-3069	5041-9610