

# Installation Note

---

## **Agilent Technologies E4406A VSA Series Transmitter Tester Firmware Upgrade Kit Using LAN**



**Agilent Technologies**

Part Number E4406-90168

Printed in USA January 2002

**Notice.**

The information contained in this document is subject to change without notice.

Agilent Technologies makes no warranty of any kind with regard to this material, including but not limited to, the implied warranties of merchantability and fitness for a particular purpose. Agilent Technologies shall not be liable for errors contained herein or for incidental or consequential damages in connection with the furnishing, performance, or use of this material.

## Description

The Agilent Technologies firmware upgrade kit allows you to upgrade the firmware of your analyzer to the latest firmware revision. The measurement personalities, operating system, and core firmware are included in the kit. Total installation time is approximately one hour.

Item Number	Agilent Part Number	Description
1	this note	Firmware Upgrade Kit Installation Note
2	8121-0545	Crossover cable
3	change periodically	Documentation and Firmware CD ROMs

## Equipment Required

- Microsoft Windows<sup>®1</sup> based personal computer with network interface card.
- Windows 98<sup>®</sup>, or NT<sup>®</sup>, or any more recent Windows<sup>®</sup> operating system
- CD\_ROM drive
- PS2 keyboard (applies if instrument serial number begins “US3”)

## Firmware Installation Procedure

Exit all open applications and insert the “Firmware and Measurements Personality” CD into the CD-ROM drive. The CD-ROM “install.htm” file should be displayed automatically. If it not displayed, select RUN and type “D:\install.htm” (where “D” is the designation for your CD-ROM drive). The instructions for installing the latest firmware in your analyzer are given in the install.htm file on the CD-ROM.

---

1. Microsoft Windows<sup>®</sup>, Windows 98<sup>®</sup>, and NT<sup>®</sup> are U.S. registered trademarks of Microsoft Corporation.

- **If the instrument fails after following the firmware installation procedure:**

Contact your nearest Agilent Technologies Sales and Service Office for assistance. Please provide the following information:

Model Number: E4406A

Serial Number: USXXXXXXXX

State that you are having trouble installing firmware using LAN.

By internet, phone, or fax, get assistance with all your test and measurement needs.

<b>Online assistance:</b> <a href="http://www.agilent.com/find/assist">http://www.agilent.com/find/assist</a>			
<b>United States</b> (tel) 1 800 452 4844	<b>Latin America</b> (tel) (305) 269 7500 (fax) (305) 269 7599	<b>Canada</b> (tel) 1 877 894 4414 (fax) (905) 282-6495	<b>Europe</b> (tel) (+31) 20 547 2323 (fax) (+31) 20 547 2390
<b>New Zealand</b> (tel) 0 800 738 378 (fax) (+64) 4 495 8950	<b>Japan</b> (tel) (+81) 426 56 7832 (fax) (+81) 426 56 7840	<b>Australia</b> (tel) 1 800 629 485 (fax) (+61) 3 9210 5947	

#### Asia Call Center Numbers

Country	Phone Number	Fax Number
Singapore	1-800-375-8100	(65) 836-0252
Malaysia	1-800-828-848	1-800-801664
Philippines	(632) 8426802 1-800-16510170 (PLDT Subscriber Only)	(632) 8426809 1-800-16510288 (PLDT Subscriber Only)
Thailand	(088) 226-008 (outside Bangkok) (662) 661-3999 (within Bangkok)	(66) 1-661-3714
Hong Kong	800-930-871	(852) 2506 9233
Taiwan	0800-047-866	(886) 2 25456723
People's Republic of China	800-810-0189 (preferred) 10800-650-0021	10800-650-0121
India	1-600-11-2929	000-800-650-1101