

8920B-07

HP 8920B RF Communications Test Set

Serial Numbers: 0000A00000 / 9999Z99999

Y2K update information.

Product requires Firmware update revision B.05.05 or greater.

To Be Performed By: Customer

Parts Required:

HP P/N	Description	Quantity
For HP 8920B Option 600(HP 83206A attached)		
HP 83206ART option R58	Firmware Upgrade Kit	1

For HP 8920B without Option 600(not used with a HP 83206A)

HP 8920BRT option R58	Firmware Upgrade Kit	1
-----------------------	----------------------	---

January 1, 1997 Serial Number:

US35320800

Situation:

Firmware revisions B.01.11 through B/05/04 are Y2K compliant for manual operation but may not be fully compliant for remote operation if running a software program using the Basic Programming command "TIMEDATE". Dates reported using the Basic Program command "TIMEDATE", will be inconsistent with dates appearing in the instrument's "CONFIG" screen "Date" field. In addition, "TIMEDATE" cannot report any date greater than 31 December 1999.

Firmware revisions B.05.05 and above are fully Y2K compliant for manual and remote operation. The "TIMEDATE" function has been corrected to report any date set between 1 January, 1994 and 31 December, 2093 and will match the "CONFIG" screen "Date" and "Time" settings.

Solution / Action:

A firmware upgrade is not required if:

The HP 8920B is being used manually (i.e. not being controlled by a software program)

A firmware upgrade is not required if:

The HP 8920B is being controlled by a software program, which does not use the "TIMEDATE" Basic Programming command. If the HP 8920B is required to report the Date while running a software program, the Basic Programming command of "CONF:DATE?" Can be used instead of the "TIMEDATE" command. The "CONF:DATE?" Command will return a date formatted as MM/DD/YY.

A firmware upgrade is required if:

The HP 8920B is being controlled by a software program, is required to work with the "TIMEDATE" command, and currently has a firmware revision of B.01.11 through B.05.04.

Hewlett Packard's Y2K Product Support Policy will cover under warranty, all HP 8920Bs shipped after January 1, 1997, and all HP 8920Bs currently covered by Extended Warranties or Support Contracts. HP 8920Bs shipped after January 1, 1997 begin with Serial Number US35320800(except refurbished units). To determine the original ship date of new or refurbished units, contact Hewlett Packard's Customer Support Center (1-800-452-4844).

Date: 31 August 1998

```
*****
*
*           MODIFICATION RECOMMENDED           *
*           -----                           *
*
*           STANDARDS: LABOR HOURS _____.5hr ____ *
* ACTION CATEGORY: ON SPECIFIED FAILURE X   IMMEDIATELY ___ *
*           AGREEABLE TIME ___ *
* LOCATION CATEGORY: CUSTOMER INSTALLABLE X   ON-SITE ___ *
*           HP LOCATION ___ *
* AVAILABILITY: PRODUCT'S SUPPORT LIFE *
* SERVICE INVENTORY: RETURN ___   SCRAP X   SEE TEXT ___ *
*           USED PARTS: RETURN ___   SCRAP X   SEE TEXT ___ *
* HP RESPONSIBLE UNTIL: 1 September 2000 *
*           AUTHOR/ENTITY: JRR / 1000 *
*           ADDITIONAL INFO: _____ *
*****
```