

S E R V I C E N O T E

SUPERSEDES: None

Agilent 8922 GSM Test Sets and 8923B DECT Test Set

Serial Numbers: See Below

New kit for Measurement Board

Duplicate Service Notes:

- 8922A-05 Serial Numbers: 0000A00000/9999Z99999
- 8922B-05 Serial Numbers: 0000A00000/9999Z99999
- 8922E-05 Serial Numbers: 0000A00000/9999Z99999
- 8922F-05 Serial Numbers: 0000A00000/9999Z99999
- 8922G-05 Serial Numbers: 0000A00000/9999Z99999
- 8922H-05 Serial Numbers: 0000A00000/9999Z99999
- 8922M-12 Serial Numbers: 0000A00000/9999Z99999
- 8922S-07 Serial Numbers: 0000A00000/9999Z99999
- 8922P-09 Serial Numbers: 0000A00000/9999Z99999
- 8922R-06 Serial Numbers: 0000A00000/9999Z99999
- 8922X-09 Serial Numbers: 0000A00000/9999Z99999
- 8923B-02 Serial Numbers: 0000A00000/9999Z99999

Situation:

Part number 08920-60431 (Measurement Board) used on several Agilent products, and supplied as kit p/n 08920-61836, has been modified. This modified version is not suitable for use in the Agilent 8922 series of GSM Test Sets or the 8923B DECT Test Set. For replacement purposes, use kit part number 08922-61909 which contains an unmodified version of the measurement board.

DATE: February 2001

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR: FH	ENTITY: E600-6423	ADDITIONAL INFORMATION:

