

8922R-01

HP8922R GSM MS Multiband Test System comprises
HP8922S #010 GSM MS Test Set and
HP83220E #010 DCS/PCS MS Test Set

Serial Numbers:
0000A00000 / 9999Z99999

Y2K update information.

Product requires firmware revision C.01.03 or later to be
Y2K compliant to HP standards (see situation).
Firmware C.01.02 or below is not Y2K compliant to HP standards.

To Be Performed By: HP-Qualified Personnel or Customer.

Parts Required:

HP P/N	Description	Quantity
08922-61184	8922R/Y F/W UPGRADE	1

Situation:

Y2K investigation has identified that the response from the BASIC
function TIMEDATE is defective. This defect exists now and a
TIMEDATE call would fail now if called in any BASIC application.
Detection of this bug has caused all 8922 instruments below
firmware B.07.07 (or C.01.03 for 8922P,R,X,Y) to be classified as
Y2K non-compliant. This bug has not been reported by customers
which implies that it has not used in any applications to date.

Failure to install the Y2K upgrade will not cause the HP8922R to
return an incorrect date/time stamp on 1st January 2000.

Solution / Action:

A firmware upgrade (ROM based) needs to be installed for
firmware above C.01.03 to meet HP Y2K compliance standards. This
fixes the TIMEDATE bug but does not affect any other date-related
processes within the instrument.

The 8922R will return the correct date/time stamp on 1st January 2000,
without modification. It is recommended that no upgrade is required.

Date: 24 August 1998

```
*****
*
*                MODIFICATION AVAILABLE                *
*                -----                *
*
*      REASON:                PERFORMANCE ENHANCEMENT  _X  *
*      -or-  SERVICE/RELIABILITY ENHANCEMENT  ___  *
*
*      ACTION CATEGORY:  AGREEABLE TIME                *
*      LOCATION CATEGORY:  CUSTOMER INSTALLABLE  _X ON-SITE  ___  *
*                        HP LOCATION  _X                *
*      AVAILABLE UNTIL:  END OF SERVICE LIFE                *
*      AUTHOR/ENTITY:  AS/E600                *
*      ADDITIONAL INFO:  _____                *
*
*****
```

Copyright Hewlett-Packard Company 1998