								89	22X	-09	
S	Е	R	V	Ι	С	Е	Ν	0	Т	Е	
А	SUPERSEDES: None Agilent 8922 GSM Test Sets and 8923B DECT Test Set										
Serial Numbers: See Below											
New kit for Measurement Board											
Duplicate Service Notes:											
89 89 89 89 89 89 89 89 89 89 89 89 89	8922A-05       Serial Numbers: 0000A00000/9999Z99999         8922B-05       Serial Numbers: 0000A00000/9999Z99999         8922E-05       Serial Numbers: 0000A00000/9999Z99999         8922F-05       Serial Numbers: 0000A00000/9999Z99999         8922G-05       Serial Numbers: 0000A00000/9999Z99999         8922H-05       Serial Numbers: 0000A00000/9999Z99999         8922H-05       Serial Numbers: 0000A00000/9999Z99999         8922N-12       Serial Numbers: 0000A00000/9999Z99999         8922S-07       Serial Numbers: 0000A00000/9999Z99999         8922P-09       Serial Numbers: 0000A00000/9999Z99999         8922R-06       Serial Numbers: 0000A00000/9999Z99999         8922R-06       Serial Numbers: 0000A00000/9999Z99999         8922X-09       Serial Numbers: 0000A00000/9999Z99999         8922B-02       Serial Numbers: 0000A00000/9999Z99999										
Si	tuation:										
pl us m	Part number 08920-60431 (Measurement Board) used on several Agilent products, and supplied as kit p/n 08920-61836, has been modified. This modified version is not suitable for use in the Agilent 8922 series of GSM Test Sets or the 8923B DECT Test Set. For replacement purposes, use kit part number 08922-61909 which contains an unmodified version of the measurement board.										
							DATE: Feb	ruary 200	)1		

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICA	TION:							
INFORMATION ONLY								
AUTHOR: FH	ENTITY: E600-6423	ADDITIONAL INFORMATION:						
© 2000 AGILENT TECI PRINTED IN U.S.A.	HNOLOGIES							

Agilent Technologies