



Agilent N1610A Service Advisor Test Tablet

Release Notes Software Release 1.40

Operating software release 1.40 for the Agilent N1610A Service Advisor Test Tablet is a new features release that adds capabilities and enhances existing features.

Agilent Technologies suggests that customers with earlier versions upgrade to version 1.40.

For more information, please refer to the *Service Advisor Test Tablet User's Manual* (N1610-90000). Or call Agilent Technologies at 800-923-7522.

Installation

If version 1.40 is not already installed in your Service Advisor Tablet, follow the instructions in the user's manual to download the software.

To check the software version in your instrument, tap the Help button on the Service Advisor screen.

Applicability

Operating software version 1.40 supports the following Agilent test instruments:

- N1610A Service Advisor Test Tablet
- N1700A Service Advisor Undercradle

New Features

Enhanced Ethernet Capability

External operations including remote control, SCPI command execution, and software downloading can now be accomplished using the Ethernet interface on the Service Advisor tablet.

Note that the Agilent N1620A 10BaseT Ethernet LAN PC card is required.

Agilent Technologies
Service Test Division
2 Robbins Road Westford MA 01886
Phone: 800-923-7522 978-266-3300
Fax: 978-266-3350

© 2000 Agilent Technologies, Inc.

Part Number: N1610-98140, Rev 1.0
May, 2000 • Printed in the USA



Agilent Technologies