

JVC

SERVICE MANUAL

CD RECEIVER

KD-LX50



Supplement

Areas suffix

J ----- Northern America

General assembly indication was wrong.
Please change the service manual of KD-LX50.
(Issue No.49561)

General assembly



VICTOR COMPANY OF JAPAN, LIMITED
 MOBILE ELECTRONICS DIVISION
 PERSONAL & MOBILE NETWORK B.U. 10-1,1Chome,Ohwatari-machi,Maebashi-city,Japan