

JVC

SERVICE MANUAL

COLOR TELEVISION

AV-A14M3_(U B)

BASIC CHASSIS

CG

Supplementary

The following item for the AV-A14M3_(U B) model were changed from those of the AV-14AM model. Therefore, this service manual describes only the items which differ from those of the AV-14AM service manual.
For details other than those described in this manual, please refer to the AV-14AM service manual (No.56091, Sep. 2000).

■ DIFFERENCE PARTS LIST

● EXPLODED VIEW PARTS LIST (Page32)

△	Ref. No.	Parts Number		Parts Name	Remarks
		AV-14AM (No.56091)	AV-A14M3(U B) (No.56092)		
△	1	LC10164-019A-H	LC10164-013A-H	FRONT CABINET	Not Interchangeable
	10	LC30347-003A-H	LC30347-001C-H	CONTROL KNOB	↑
△	13	LC20377-001B-H	LC20413-003A-H	RATING LABEL	↑
	17	LC30348-003A-H	LC30348-001B-H	POWER KNOB	↑

● PACKING PARTS LIST (Page39)

△	Ref. No.	Parts Number		Parts Name	Remarks
		AV-14AM (No.56091)	AV-A14M3(U B) (No.56092)		
△	1	GG10056-020A-H	GG10056-014A-H	PACKING CASE	Not Interchangeable
	6	LCT0733-001A-H	LCT0650-001A-H	INST BOOK	↑
	7	LCT0734-001A-H	LCT0651-001A-H	DIGEST MANUAL	↑
	10	—————	CP30702-001	POS,SERIAL LABEL	Addition
		—————	QAM0054-001	CONVERSION PLUG	↑
		—————	CM36141-010-H	WARNING LABEL	↑

● **MAIN PWB PARTS LIST (Page34-37)**

△	Symbol No.	Parts Number		Parts Name	Remarks
		AV-14AM (No.56091)	AV-A14M3(U B) (No.56092)		
		SCG-1248A-H2	SCG-1261A-H2	MAIN PWB	Not Interchangeable
	R1565	—————	NRSA02F-4421X	MG R	Addition
	R1566	—————	NRSA02F-562X	MG R	↑
	R1981	—————	NRSA02J-273X	MG R	↑
	R1982	—————	NRSA02J-103X	MG R	↑
	R1983	—————	NRSA02J-823X	MG R	↑
	R1984	—————	NRSA02J-183X	MG R	↑
	C1562	—————	QETN1HM-106Z	E CAP.	↑
	C1981	—————	QETN1HM-475Z	E CAP.	↑
	D1561	—————	1SR124-400A-T2	SI.DIODE	↑
	D1562	—————	MTZJ7.5S-T2	ZENER DIODE	↑
	D1985	—————	1SS355-X	SI.DIODE	↑
	D1986	—————	1SS355-X	SI.DIODE	↑
	Q1982	—————	2SC2785/JH/-T	SI.TRANSIS	↑

JVC

VICTOR COMPANY OF JAPAN, LIMITED
HOME AV NETWORK BUSINESS UNIT 1106 Heta, Iwai-city, Ibaraki-prefecture, 306-0698, Japan

